

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7801)

Set a stone 14x10x4 ins., 10" in the ground, for 1/4 sec. cor. marked 1/4 on W. face; from which

A B.Oak 6" dia., bears S.80 3/4°W., 45 lks. dist. mkd. 1/4 S BT.

A B.Oak 10" dia., bears N.40 1/4°E., 20 lks. dist. mkd. 1/4 S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Feb/March 1966 - C.S. File 54/20-29

Found - No trace of corner stone.

Orig. 6" now 10" B.Oak S.80 3/4°W., 29.7 ft., very rotten, scribe visible "1/4S".

Orig. 10" now 13" B.Oak N.40 1/4°E., 13.2 ft., opened for scribe "B". Center of tree is rotted out.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 4 W

1/4 S35 | S 36

1966

New BTs- 5" Pine, West, 32.1 ft. scribed 1/4 S CS BT.

9" Pine N.46°E., 19.1 ft. scribed 1/4 S36 CS BT.

Fd. OK, April 1993 by R. Brown - M 112-72

Fd. OK, Nov. 1996 by G. Nygren - M 124-34