

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7803)

-----  
 Set a stone 14x12x8 ins., 10" in the ground for ¼ sec. cor. marked ¼ on N. face; from which

A Fir 36" dia., bears S.67 3/4°E., 7½ lks. dist. mkd. ¼ S BT.

A Fir 12" dia., bears N.25 3/4°W., 17 lks. dist. mkd. ¼ S BT.

BLM remonumentation by Lynn M. Roseberry, Cadastral Surveyor, under Group #1000, surveyed Aug. 1980 - (DCSO records Vol. 45 Page(s) 17450)

-----  
 The ¼ sec. cor., monumented with the original basalt stone, 14 x 12 x 8 ins., loosely set 3" in the ground, mkd. ¼ on W. face, from which the remains of the original bearing trees:

A Fir 42" dia., bears S.67 3/4°E., 7½ lks. dist., with healed blaze.

A decayed Fir stump 12" dia., bears N.25 3/4°W., 17 lks. dist. with scribe marks ¼ S BT visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 4 W  
                   1/4  
                   S 26 | S 25  
                   1980

from which a new bearing tree

A Fir 6" dia., bears N.27°W., 21 lks. dist. mkd. ¼ S26 BT. Deposit corner stone alongside iron post.

Survey by Thomas H. Mehl III, LS #749 - For: Gregory Timber -Sept. 27, 1990 - C.S. File 63/104-29

-----  
 Found - Iron post, 2½" dia. with 1980 BLM brass cap. Orig. BT, 40.6" DBH D.Fir, bears S.67 3/4°E., 7½ lks. dist. with healed blaze.

Rotten stump of orig. BT, bears N.25 3/4°W., 17 lks., old slab is now detached from stump, but scribing is evident.

1980 BLM BT, 6" D.Fir bears N.27°W., 21 lks. dist. mkd. ¼ S26 BT, now laying approx. N.10°W.

New BT - 8.2" DBH D.Fir bears N.45°30'E., 23.0 ft. with blaze scribed "¼ LS 749 BT"

No acceptable BTs found in sec. 26. Corner lies on W. facing slope approx. 100 ft. W. of road. (31-4-27)

(Cont. Next Page)

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Survey by Gregory D. Lang - For: Silver Butte Timber Co. -  
April 1995 (filed June 1996) - M 125-6

-----

Found - Brass cap at  $\frac{1}{4}$  corner.  
42" Fir bears S.67  $\frac{3}{4}$ °E., 7 $\frac{1}{2}$  lks.  
26" Fir snag, location tag bears N.82°W., 14.7 ft.  
No apparent record.  
10 $\frac{1}{2}$ " Fir bears S.45 $\frac{1}{2}$ °E., 23.05 ft.  
9" Fir, face down, bears approx. N.25°W., 13.7 ft.

Fd OK by Kris DeGroot, 1/2006 - M 149-41