

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7809-10)

Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on W. face; from which
A Fir 6" dia., bears S.35 1/2°W., 11 lks. dist. mkd. 1/4 S BT.
A Laurel 7" dia., bears S.8°E., 51 lks. dist. mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
Wit: R.G. Boyd - Oct. 7, 1959 - C.S. File 42/391-45

At midpoint, SET 3/4" x 30" Iron pipe, from which
5" Laurel bears N.83°E., 32.0 ft. mkd. 1/4 S12 T31S BT.
5" Laurel bears S.37°W., 8.3 ft. mkd. 1/4 S11 T31S R4W BT.
5" Laurel bears S.67°W., 7.1 ft. mkd. 1/4 S11 BT.
SW. corner 12 bears South 2596 ft.
NW. corner 12 bears North 2596 ft.

David Edwards - For: Roseburg Resources Co. - 5/2010 - M
160-63

Found - 3/4" dia., iron pipe fd. in poor condition. Replaced
with rebar & alum. cap.
8" Madrone S.37°W., 8.3' w/partial bark scribe.
New BTs- 9" dia., Fir S.75°E., 6.1'
12" dia., Fir N.47°W., 22.8'
Set 6' steel post 2' south.