

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7804)

Set a stone 14x12x8 ins., 10" in the ground, for 1/4 sec. cor. marked 1/4 on N. face; from which
A Fir 6" dia., bears S.11°W., 9 1/4 lks. dist. mkd. 1/4 S BT.
A Fir 10" dia., bears N.85 1/2°E., 35 lks. dist. mkd. 1/4 S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: R.G. Boyd - Oct. 16, 1958 - C.S. File 42/391-5

Determined by O.B.Ts:
10" Fir bears S.11°W., 6.1 ft., found scribe.
13" Fir bears N.87°E., 23.5 ft.
At corner point found stone and SET 1"x30" IP, from which
11" Laurel bears N.51°W., 18.2 ft. mkd. 1/4 S24 BT.
12" Cedar bears S.53°E., 37.5 ft. mkd. 1/4 S25 BT.
Road bears South, 28.0 ft. dist.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - April 1966 - C.S. File 54/20-42

Found - Iron pipe at 1/4 corner.
Orig. 10" Fir S.11°W., 6.1 ft., scribe visible, tree almost gone.
Orig. 13" Fir N.87°E., 23.5 ft., good scar, poor condition.
11" Laurel, now 12", N.51°W., 18.2 ft., scribing visible.
12" Cedar S.53°E., 37.5 ft., tree down.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 4 W
1/4 S 24
S 25
1966

Brass cap set alongside iron pipe.
New BT - 52" D.Fir N.51°E., 27.0 ft. scribed 1/4 S24 CS BT.

David Edwards - For: Roseburg Resources Co. - Feb. 2011 - M162-12

Found - Brass cap
12" dia. Fir S.11°W., 6.1 ft with no marks visible.
53" dia. Fir snag with healed blaze N.51°E. 27.0 ft.
New BTs- A 6" dia. Fir bears N.12°E., 13.0 ft.
A 5" dia. Madrone bears S.50°W., 16.1 ft.
A 6 ft steel post is set 2 north.