

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7690)

Set ¼ sec. post, from which
A Fir 16" dia., bears N.50°E., 31 lks. dist.
A Fir 18" dia., bears S.32°W., 19 lks. dist.

Cor. Fd. and used GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7800)

Douglas Co. Surveyors Office - James Byron - For: Douglas Co. Road Dept. for Rd. #36 - Feb.7, 1957 - C.S. File drawer 48 Rd. #36

Found - 2" x 2" sq. post at corner.
Orig. SW. BT, has visible scribe marks, stump.
Orig. NE. BT, has burned face, stump.
Both BTs check bearing and distance.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S
R4W ¼ S36 | S31 R3W
1957
Corner under 3 ft. log.
New BTs- 16" W.Fir bears N.21°E., 79.5 ft. scribed ¼ S31 T31S
R3W CS BT.
12" W.Fir bears N.83½°W., 53.2 ft. scribed ¼ S36
T31S R4W CS BT.

Douglas Co. Surveyors Office - Larry Monrean, Deputy - John Powell, crew - Dec. 30, 1981 - C.S. File 61/30-6

Found - Original post not found.
1" dia., I.P. with 1957 DCSO brass cap attached, properly marked. Monument is firmly set 10" above ground.
Orig. 16" Fir now stump 28" dia., with fragmentary scribing visible, bears N.50°E., 20.5 ft. to face.
An 18" orig. Fir now a stump 28" dia. with scribing "¼ S" visible, bears S.43°W., 12.5 ft. to face. (Rec. S.32°W.)
A W.Fir 16" now 18" with well healed double blaze bears N.21°E., 79.5 ft.
A W.Fir 12" now 18" with well healed double blaze, bears N.83½°W., 53.2 ft.

(Cont. Next Page)

