

PRIMARY CORNER DESCRIPTION Sec Cor for 25 & 36; 30 & 31, T31-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 18 Page(s) 7690)

Set post, cor. to secs. 25, 30, 31 and 36, from which
A Fir 24" dia., bears N.28°E., 16 lks. dist.
A Laurel 16" dia., bears S.72°E., 8 lks. dist.
A Fir 10" dia., bears S.51°W., 12 lks. dist.
A Fir 12" dia., bears N.25°W., 29 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 18 Page(s) 7792)

The Sec. cor., which is a post, considerably decayed, marked T31S S30 on NE.; R3W S31 on SE.; R4W S36 on SW.; and S25 on NW. faces, with 5 notches on N. and 1 notch on S. edges; I remove this post and set a stone 22x18x7 ins., 16" in the ground for cor., marked with 5 notches on N. and 1 notch on S. edges; from which

A Laurel 16" dia., bears S.72°E., 8 lks. dist. mkd. T31S R3W S31 BT.
A Fir 12" dia., bears N.25°W., 29 lks. dist. mkd. T31S R4W S25 BT.

The witness trees in secs. 30 and 36 are blown over and the Laurel witness tree in sec. 31 is dead. I, therefore, mark 3 new witness trees as follows:

A Fir 20" dia., bears N.6¼°E., 34½ lks. dist. mkd. T31S R3W S30 BT.
A Fir 10" dia., bears S.26½°E., 47½ lks. dist. mkd. T31S R3W S31 BT.
A Cedar 26½" dia., bears S.12¼°W., 33 lks. dist. mkd. T31S R4W S36 BT.

Douglas Co. Surveyors Office - Geo Wenderoth, Deputy - Frank Loso, witness - Dec. 1947/Feb. 1948 - M 27-14

Drive 1" Pipe for corner and find 2 old BTs:
20" Fir bears N.13°30'E., 22.7 ft. dist.
14" Fir bears N.12°50'W., 19.4 ft. dist.
Marked - 24" Cedar, bears S.7°20'W., 20.6 ft.
18" Fir bears S.19°12'E., 47.5 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & J. Brady, crew - Jan. 14, 1966 - C.S. File 52/63-53

Found - 24" Cedar, now dead snag, S.7°W., 20.6 ft., scribe visible "CS BT".

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 25 & 36; 30 & 31, T31-3

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

18" D.Fir S.19°E., 47.5 ft., gone.
 20" D.Fir now 25", N.13½°E., 22.7 ft. This tree in slope bank of road.
 14" D.Fir, now 17", N.13°W., 19.4 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office 1966

		T 31 S	
R S 25	S 30	R	
4 S 36	S 31	3	
W	T 32	S	W

New BTs- 19" D.Fir S.16°E., 80.1 ft. mkd. T31S R3W S31 CS BT.
 8" D.Fir S.83°W., 17.5 ft. mkd. T31S R4W CS BT.
 This corner is on edge of new road.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - J.M. Powell, crew - Dec. 30, 1981 - C.S. File 61/30-5

Orig. stone monument and post corner monuments not found. Also not found is Wenderoth's 1" I.P.
 Found - Brass cap on a 1" x 36" I.P., properly marked, laying on its side in a fill area. (The orig. ground in this area is covered with debris. (road fill))

As the orig. BT calls do not fit well, a distance intersect is used to determine the position from which the following measurements were made:

- Orig. Fir 12" now 27", bears N.9°W., 19.1 ft. (Rec. N.25°W.) Blaze is well healed, we open and find scribing "S25 R4"
- From orig. survey renewal of corner, a 20" now 30" Fir with well healed blaze, bears N.16°E., 22.8 ft., we open blaze and find scribing "W 3".
- The 26½" Cedar, a snag during 1966 visit, is now down with some scribe marks visible on unhealed face. The rec. brg. & dist., S.12¼°W., 21.8 ft., falls on the root wad of the BT.
- A Fir 18", now a stump, (size indeterminate) with fragmentary scribing visible, bears S.22°E., 48.0 ft. (Rec. S.19°12'E., 47.5 ft.)
- A D.Fir 19" now 21" with well healed double blaze, bears S.16°E., 80.1 ft.
- A D.Fir 8" now 14" with well healed double blaze, bears S.86°W., 17.2 ft. (Rec. S.83°W., 17.5 ft.)
- A "not of record" D.Fir 22" dia., bears North 23.9 ft., has a yellow tag mkd. "31S 3W KB 8/20/39"

The found monument is set at position as determined by the previous note. (sketch in C.S. File)

cont.

TOWNSHIP 31 RANGE 04 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec Cor for 25 & 36; 30 & 31, T31-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd. OK, April 1993 by R. Brown - M 112-72

Carl Sweeden - For: Perpetual Forest Co - 3/2011 - M162-13

Found - 2½" BC, 1966 DCSO
23" D.Fir BT, N.9°W. 19.5' hole in scarred face, tag
28" D.Fir BT, N.4°E. 23.9', scar, tag "This tree
noted as not of record"
32" D.Fir BT, N.16°E. 22.8', faint scar vis., tag
18" D.Fir BT, S.86°W. 17.2', scar vis. Tag
24" D.Fir BT, S.16°E. 80.1', scar, 2 tags
Rotted stump remains, S.22°E. 48.0'
Cedar BT, down per rec., S.12°W. 21.8' to root hole

FD. Ok by C. Sweeden, 3/2012 - M163-35

FD. Ok by R. Quimby, 3/2018 - C.S. 65/101-23