

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Geo. W. Hyde under contract # 54, dated Feb. 19, 1855. (DCSO records Vol. 19 Pg. 7879)

Set a post from which:

- A Hemlock, 14" dia. bears S.67°W., 32 lks.
- A Fir, 40" dia. bears N.63°E., 35 lks.
- A Fir. 36" dia. bears N.62°W., 71 lks.
- A Fir, 30" dia. bears S.68°E., 50 lks.

Bruce Shaner - for Bate Lumber Co. Feb. 1964 M27-36.

Set 5/8" x 36" Iron Rod, from which a:

- 44" D.Fir stump, Orig. BT with scribes vis. bears N.62°W., 46.9 ft.
- 42" D.Fir stump, Orig. BT with old rotten face, bears S.68°E., 33.0 ft.

New BTs -

- 48" D.Fir bears S.45°E. 58.6 ft. scribed "T31S R6W S25 BT"
- 14" D.Fir bears N.46°E. 56.5 ft. scribed "T31S R5W S19 BT"
- 12" D.Fir bears S.20°E. 37.3 ft. scribed "T31S R5W S30 BT"

Doug. County Surveyors Office - John M. Powell, Frank Jones & Joe Brady - May & June 1966, C.S. File 54/25-30

Found - 48" Fir, S.45°E., 58.6 ft. scribe vis. (S.B. S.45°W)
14" Fir N.46°E., 56.5 ft. scribe vis.
12" Fir S.20°E., 37.3 ft. scribe vis.
Orig. 44" Fir stump N.62°W., 46.9 ft. opened for scribing.

Iron Rod at Sec. Cor. flush with ground.

Set - Brass Cap at Cor. (alongside iron rod) Marked:

COUNTY SURVEYORS OFFICE

R	T31S	R
6	S24 S19	5
W	S25 S30	W
1966		

Note - All BTs in good condition, logging road is north 25'

B.L.M. Resurvey - James E. Jelly, Wayne L. Rogers, under Group #1101, surveyed, Sept. 1982 through May 1983. (DCSO records Vol 45 Pg. 17493)

Found - County Surveyors Office Brass Cap properly marked projecting 10" above ground.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor 19 & 30; 24 & 25 T31-6.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

- A sawed fir stump, 48" dia. bears N.62°W., 71 lks. with scribe marks S24 vis. on opened blaze. (Orig.)
- A fir, 15" dia. bears N.47 3/4°E., 86 lks. with fragmentary scribe marks visible on partially healed blaze. (Shaner)
- A fir, 18" dia. bears S.21¼°E., 58 lks. with healed blaze. (Shaner)
- A fir, 47" dia. bears S.47°W., 93 lks. with fragmentary scribe marks visible on partially healed blaze. (Shaner)

New BT -

A Grand Fir 5" dia. bears N.84°W., 54 lks. mkd. "XBT"
Note - The corner is located 50 lks. south of a graveled road, 25 lks. wide, bears N.65°W., and S.80°E.

Douglas Co. Surveyors Office - Fd OK, 1/7/92, C.S. 64/23-1

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2078, surveyed June/Sept. 2004 (DCSO rec. Plat 31-6 2011 & Vol. 56 pg(s) 22322)

The cor. of secs. 19, 24, & 25 and 30 on the E bdy of the Tp (31-6) monumented with an iron post, 2½" dia., firmly set, projecting 10" above the ground, (alongside of which is an iron rod, 5/8" dia., firmly set, flush with the ground, set by Shaner in 1964 with brass cap (properly) mkd. from which the remains of an orig. BT

A sawed fir stump, size indeterminate, bears N.62°W., 46.9 ft. with scribe marks T31S R6W S24 visible on open blaze.

and the BTs mkd by Shaner reported by Jelley & Rogers in 1982

A fir, 18" dia., N.47¾°E., 56.8 ft. with a healed blaze.

A fir 25" dia., S.21¼°E., 38.3 ft. with a healed blaze.

A fir 51" dia., S.47°W., 61.4 ft. with a healed blaze.

and a BT mkd by Jelley & Rogers

A fir, 9" dia., bears N.84°W., 35.6 ft. with a healed double blaze.

Corner is located 21.3 ft. S of a graveled road, 15 ft. wide, which bears S.83°E., and N.83°W.