

PRIMARY CORNER DESCRIPTION Corner to Sections 5, 6, 7, & 8.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - George W. Hyde under Contract #54 dated Feb. 19, 1855 (DCSO records, Vol. 19 Page 7886)

Marked a Fir, 18" dia. for corner, from which:
A Fir, 12" dia. bears N.10°W., 4 lks. dist.
A Fir, 10" dia. bears N.30°E., 3 lks. dist.
A Bull Pine, 14" dia. bears S.75°E., 22 lks. dist.
A W.Cedar. 30 x 30" dia. bears S.22°E., 46 lks. dist.

B.L.M. Resurvey - John M. Jelley, Lynn M Roseberry, Floyd A Brooks, under Group #s 320 & 614, surveyed, June 1966 through May 1968. (DCSO records Vol. 35, Pg.14378-79)

Found - Original corner tree, a Fir, 33" dia. with a healed blaze on the SE and SW face, from which the original bearing trees:

A Fir, 20" dia. bears N.30°E., 3 lks. dist., with a healed blaze.
A Pine, 26" dia. bears S.75°E., 24 lks. dist., with a healed blaze. (rec. 22 lks.)
A Cedar, 38" dia. bears S.22°E., 46 lks. dist., with fragmentary scribe marks visible on open blaze.
A Fir, 19" dia. bears N.10°W., 4 lks. dist., with a healed blaze.

New Accessories -

A Madrone, 21" dia. bears S.51°W., 60 lks. dist. marked: T31S R5W S7 BT.
An iron post, 28" long, 2½" dia. set 24" in ground for reference monument, bears S.30°E., 5 lks. dist., with brass cap marked: T31S R5W S8 RM 1966 and an arrow pointing to the corner.

Douglas Co. Surveyors Office - Gary L. Langlitz, Clell E. Goodwin, A. Vic Cangie, M.Lenora Ladig. C.S. File 57/39-35 Dec. 16, 1975.

Found - Orig. 18" now 33" corner tree with healed blazes on SE and SW faces from which original bearing trees are located as follows:

12" now 19" D.Fir alive and well healed blaze bears N.10°W., 2.6 ft. (orig.)
10" now 21" D.Fir, alive and well healed, bears N.30°E., 2.0 ft. (orig.)
14" now 26" P.Pine, alive and well healed bears S.75°E., 15.8 ft. (orig.)
30" I.Cedar, now a 40" stump with scribe marks visible on opened blaze, bears S.22°E., 30.4 ft. (orig.)

(Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Corner to Sections 5, 6, 7, 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - (cont.)

A 2½" dia. iron pipe firmly set with brass cap attached properly marked (A BLM 1966 Brass cap) bears S.30°E., 3.3 ft.

A Madrone BT also marked in 1966 by BLM has been destroyed by road construction.

New Accessories -

14" D.Fir bears N.12½°W., 52.2 ft. scribed "T31S R5W S6 CSBT" on a double blaze.

16" I.Cedar bears N.55°E., 45.9 ft. scribed "T31S R5W S5 CSBT" on a double blaze.

This corner is located approx. 30 ft. north of a newly constructed road. Compass declination 20°E.

BLM dependent resurvey by Daniel E. Weller, Cadastral Surveyor, under Group #1884, surveyed July/Sept 1998. (DCSO records Vol. 53 Page(s) 20481)

The cor. of secs. 5, 6, 7, and 8, monumented with the remains of the original corner tree, a fir snag, 34" dia., with healed blaze on SE. and SW. sides, from which the remains of the original bearing trees:

A fir, 22" dia., bears N.30°E., 3 lks., with a healed blaze.

A pine, 26" dia., bears S.72¼°E., 22 lks., with a healed blaze. (Record, S.75°E., 24 lks.)

A cedar stump, 40" dia., bears S.22°E., 46 lks., with no marks visible on opened blaze.

A fir snag, 19" dia., bears N.10°W., 4 lks., with a healed blaze.

and bearing trees mkd. by Langlitz, in 1975

A cedar, 17" dia., bears N.54°E., 70 lks., with scribe marks 31 R5 5CB visible on partially healed blaze.

A fir, 20" dia., bears N.15¼°W., 80 lks., with a healed double blaze.

and a new accessory

A stainless steel post, 28" long, 2½" dia., set 21" in the ground for a reference monument, bears S.40°E., 5.6 lks., with brass cap mkd. RM 3.7 FT TO COR 1998 and an arrow pointing to the cor.

FD. orig. corner tree, BC RM & 6 BTs by R. Quimby 6/2016 - M171-12A&B

continued next page

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Corner to Sections 5,6,7,8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 3/19/25 - C.S. File 67/60-9

Found - Original corner tree 34" Fir snag 3 1/8" brass cap reference monument.
23" D.Fir N.30°E. 2.0' (rec 3 lks) healed blaze.
28" Pine S.72 1/4°E. 14.5' (rec 22 lks) healed blaze.
30"x2' rotted broken cedar stump S.22°E. 30.4' (rec 46 lks) no marks on open blaze.
19"x9' fir snag N.10°W. 2.7' (rec 4 lks) with healed blaze.
20" I. Cedar N.54°E. 46.2' (rec 70 lks) vis. scribs on partly healed blaze "R5" B
23" D.Fir N.15 1/4°W. 52.8' (rec 80 lks) healed double blaze.
3 1/8" brass cap proj 3" S.40°E. 3.7' (rec 5.6 lks) mkd RM 3.7' to cor 1998 → pointing to corner.

Notes - Mon is approx 30' north of gravel road.

Compass decl. 14 1/2°E.

OCRS COORDINATE SYSTEM

COTTAGE GROVE-CANYONVILLE ZONE

N 461712.771 E 4163351.519