

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5 of T32-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Geo. W. Hyde, under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 19 Page(s) 7883)

-----  
Set post cor. to secs. 4, 5, 32 and 33, from which  
A Fir 12" dia., bears S.39°W., 98 lks. dist.  
A Fir 9" dia., bears N.31°W., 13 lks. dist.  
A Fir 8" dia., bears S.53°30'E., 86 lks. dist.  
No trees accessible NE.

GL0 survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8604)

-----  
The cor. of secs. 4, 5, 32 and 33, which being gone, I replace it by setting a granite stone 16x12x10 ins., 11" in the ground, mkd. with 4 notches on E. and 2 notches on W. edges, and witnessed as described by the surveyor general.

BLM resurvey by Joseph Gawron and Norman McDonald under Group #472, Surveyed June/July 1962 (DCSO records Vol. 32 Page(s) 13244-45)

-----  
The Sec. cor. determined from two original bearing trees:  
A Fir 22" dia., bears S.39°W., 98 lks. dist., mkd. T32S R5W S5 BT.  
A Fir 25" dia., bears N.21°W., 13 lks. dist., with a healed blaze. (Record, N.31°W.)

At the corner point  
Set an iron post 30" long, 2½" dia., 6" in the ground to solid rock, supported in a mound of stone, 8 ft. base to top, with brass cap marked:

T 31 S R 5 W  
S 32 | S 33  
S 5 | S 4  
T 32 S  
1962

from which  
A Fir 13" dia., bears N.14½°E., 68 lks. dist., marked T31S R5W S33 BT.  
A Fir 16" dia., bears S.38°E., 80 lks. dist., marked T32S R5W S4 BT.  
A Fir 8" dia., bears S.65½°W., 62 lks. dist., marked T32S R5W S5 BT.  
A Fir 14" dia., bears N.41°W., 29 lks. dist., marked T31S R5W S32 BT.

(Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5 of T32-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy -  
P. Earle - Jan. 30, 1974 - C.S. File 56/43-11

-----  
Found - BLM cadastral brass cap, lying on ground near  
uprooted tree. I remove cadastral marker and  
Set Brass cap cemented in drill hole at base of a small rock  
outcrop at record bearing and distances from an original:  
12" now 24" D.Fir bearing S.39°W., 64.7 ft.  
previously opened with scribing "2S 5W" visible.  
Brass cap marked:

Douglas County Surveyor  
T 31 S R 5 W  
S 32 | S 33  
S 5 | S 4  
T 32 S R 5 W  
1974  
Office

from which:

14" D.Fir bears N.11°E., 41.9 ft. (Rec. N.14½°E., 44.9  
ft.) scribing visible in partially healed blaze.

16" D.Fir down, bears S.30°E., 56.8 ft. (Rec. S.38°E.,  
52.8 ft.) scribing T32S R5W S4 BT visible.

10" D.Fir bears S.66°W., 45.3 ft. (Rec. S.65½°W., 40.9  
ft.) with healed blaze.

14" D.Fir down, bears N.50°W., 22.0 ft. (Rec. N.41°W.,  
19.1 ft.) blaze and scribing visible.

New BT and bearing object:

An "X" chiseled in a vertical rock face bears S.24½°E.,  
58.6 ft.

A 22" D.Fir bears N.74°W., 45.4 ft. scribed "T31S R5W S32  
CS BT."

The NW O.B.T., called for in resurvey field notes, now down,  
bears approx. N.38°W., 8 ft. (Rec. N.31°W., 8.6 ft.)

David Edwards - For: Roseburg Resources - Dec. 2018 - M175-11

-----  
Found - brass cap  
22" dia., Fir bears N.11°E., 41.9'  
An "X" chiseled in rock bears S.24½°E., 58.6'  
13" dia., Fir bears S.66°W., 45.3'  
24" dia., Fir bears N.74°W., 45.4'  
All BTs with healed blazes.  
Set - A six ft steel post 2 ft north.