

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7922)

Set a basalt stone 15x14x6 ins., 10" in ground for ¼ sec. cor., marked ¼ on W. face, from which
A Fir 22" dia., bears N.62°E., 24 lks. dist. mkd. ¼ S BT.
A Fir 5" dia., bears S.75°W., 18 lks. dist. mkd. ¼ S BT.

Survey by Victor S. King - For: Bate Lumber Co. - Wit: Chester C. Jones - Feb. 5, 1959 - C.S. File 42/425-2

Found - 8" Fir S.75°W., 18 lks. with scribing visible.
Set 1½" Iron pipe 3 ft. long in a mound of stones, from which I set the following new bearing trees:
12" Fir S.38°E., 3.6 ft. scribed ¼ S33 BT.
24" Fir N.75°W., 16.0 ft. scribed ¼ S32 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady - May 1966 - C.S. File 54/25-8

Found - 1½" Iron pipe in mound of stone.
Orig. 8" Fir now 16", S.75°W., 11.8 ft. Tree opened for scribe.
12" Fir now broken, S.38°E., 3.6 ft. shows good scar.
24" Fir now down, N.75°W., 16.0 ft. shows good scar.
New BTs - 16" D.Fir N.70°W., 19.8 ft. scribed ¼ S32 CS BT.
16" D.Fir S.13°E., 29.6 ft. scribed ¼ S33 CS BT.
Road bears West, 80.0 ft.

David Edwards - For: Roseburg Resources - March 2015 - M169-18

Found - 1½" dia. IP in mound of stones per CS. 42/425.
Orig. BT S.75°W. is down & rotted.
1966 DCS BTs fd.
24" dia. fir bears S.13°E., 29.6 ft.
22" dia. fir bears N.70°W., 19.8 ft.
Both with healed blaze
A six ft steel post is set 2 ft S.89°W.

Fd. as per record 12/2018 by D. Edwards M175-11