

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W. P. Wright, under Contract #281 dated May 16, 1878 (DCSO records Vol. 19 Page(s) 7889)

-----  
Set post 4 x 3 ins. dia., x 3½ ft. long, 18" in ground for ¼ sec. cor., from which

A Laurel 6" dia., bears S.79°W., 48 lks.

A Fir 10" dia., bears N.26°W., 12 lks.

Douglas Co. Surveyors Office - George J. Wenderoth, Deputy - May 23, 1958 - C.S. File 49/92-3

-----  
Found this corner and drove 1" iron pipe for corner.

26" Fir N.26°W., 7.9 ft., good.

50" Cedar S.65°W., 36.1 ft., good.

BLM Corrective Resurvey - John Jelley, Lynn Roseberry, Floyd Brooks, Under Group #s 320 and 614, - Surveyed June 1966 through May 1968. (DCSO records Vol. 35 Page(s) 14372)

-----  
The ¼ sec. cor., perpetuated and recorded by Wenderoth, in 1958, monumented with an iron pipe 1" dia., protruding 12" above ground, firmly set, from which the remaining original bearing tree:

A Fir 22" dia., bears N.26°W., 12 lks. dist., with a healed blaze.

and a bearing tree reported by Wenderoth:

A Cedar 50" dia., bears S.65°W., 57 lks. dist., with scribe mark B visible on opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. dia., 22 ins. in the ground, with brass cap mkd: T 31 S R 5 W

¼  
S 5 | S 4  
1966

from which a new bearing tree

A Hemlock 13" dia., bears S.55½°E., 32 lks., mkd. ¼ S4 BT.  
Deposit the iron pipe alongside the iron post.

Ron Quimby - For: C & D Lumber Co. - Nov. 2014 - M166-22

-----  
Found - Brass cap per 1966-1968 BLM resurvey  
20" Hemlock S.55°E., 21.1' healed face  
66" Cedar S.65°W., 37.6' healed face  
30" Fir N.26°W., 7.9' healed face

New - 15" Hemlock N.46°E., 6.9' scribed "¼ S4 BT"

Fd. BLM BC & 4 BTs by R Quimby 6/2016 - M171-12 A&B