

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 33; and S. 4 of T32-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Geo. W. Hyde, under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 19 Page(s) 7883)

Set ¼ sec. post, from which
A Laurel 6" dia., bears S.55°E., 46 lks. dist.
A Live Oak 4" dia., bears N.49°E., 7 lks. dist.

Survey by Richard Templin - For: Arrant Lumber Co. - April 8, 1977 - C.S. File 58/93

(Set by single proportionment)
Set 5/8" x 30" Iron rod 25" in the ground with a yellow plastic cap marked: "TEMPLIN RE 3024"
from which:
A Ponderosa Pine 2" bears N.03°E., 14.5 ft. mkd. ¼ X.
A Chinquapin 10" bears N.68°E., 60.1 ft. mkd. ¼ S33 RE3024 BT.
This corner falls on the South edge of an old skid road in the middle of a large clear cut logging unit. No evidence of original corner found.

David Edwards - For: Roseburg Resources - Dec. 2018 - M175-11

Found - 5/8" IR per C.S. 58/93-1
Both BTs per C.S. 58/93 are dead
New BTs- 15" dia., fir scribed "¼ S33 BT" bears N.37°E. 14.9'
15" dia., fir scribed "¼ S4 BT" bears S.35°E., 14.2'
Six ft steel posts set 2' north and 2' west.