

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 456 surveyed July 28, 1882 (DCSO rec. Vol. 19 Page 7914)

Set a stone 13x12x10 ins., 8" in ground, for the ¼ sec. cor., marked ¼ on the W. face, from which

A Fir 40" dia., bears S.67°W., 63 lks. dist. mkd. ¼ S BT.

A Fir 26" dia., bears S.56°E., 48 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John Powell, Frank Jones and Terry Connell - June 1966 - C.S. File 54/25-11

Found - 1½" Iron pipe at corner.

40" Fir, blown down, S.67°W., 41.6 ft.

26" Fir, now 38", S.56°E., 31.7 ft. bark scribe visible.

Set Brass cap alongside I.pipe, mkd: County Surveyors Office

T 31 S R 5 W

¼ S 33 | S 34

1966

New BTs -9" Maple S.44°W., 22.1 ft. mkd. ¼ S33 CS BT.

9" Live Oak N.48°E., 39.3 ft. mkd. ¼ S34 CS BT.

(Research by DCSO office July 1994, could find no source for the found 1½" iron pipe.) VL

David Edwards - For: Roseburg Resources - Dec. 2018 - M175-11

Found - Brass cap

9" dia., live oak w/healed blazes bears N.48°E., 39.3'

40" fir w/visible bark scribe bark scribe bears S.56°E., 31.7'

12" dia., maple w/no visible marks bears S.44°W., 22.1'

Adam DeGroot - For: Silver Butte Timber Co. - Dec. 2019 - M171-74

Found - A 1½" IP by DCSO in 1966, firmly set and projecting 18" above ground in a 3 ft dia. loose talis stone mound, with a 2½" brass cap properly mkd. per the record, with BTs per the 2018 Edwards survey M175-11. The corner was visited and BTs repainted by others in SEPT. 2019.

Lat: 42°49'59.88397"N Long: 123°17'14.07125"W

continued next page

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ron Quimby - Crew: N. Fromdahl & L. Heddens - 3/2020 - C.S.
File 65/106-3

Found - DCSO Brass cap (properly marked)
12" Live Oak N.48°E., 39.3 ft healed blaze.
40" Fir S.56°E., 31.7 ft. visible bark scribe.
12" Maple S.44°W., 22.1 ft. no marks.
New - 8" Madrone N.25°W., 24.8 ft. scribed ¼ S33 BT.
Note - Area badly burnt 2019
Compass decl. 15½°E.