

PRIMARY CORNER DESCRIPTION 1/4 Cor for Secs. 15 and 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7918)

-----  
Set a basalt stone, 16x10x8 ins., 10" in ground, marked with ¼ on N. face for the ¼ sec. cor., from which  
A Fir 6" dia., bears S.5°E., 21 lks. dist. mkd. ¼ S BT.  
A Fir 30" dia., bears N.15°W., 30 lks. mkd. ¼ S BT.

Survey by Bruce Shaner, L.S. #430 - For: Richard McKenzie - June 1992 - M 112-49

-----  
No evidence of original corner, so by proportional measurement  
I Set 3" Brass cap on a 2' x 30" galv. I.Pipe marked "T31S R5W W.M. ¼ S15 S22 RLS 430 1992".  
from which  
10" D.Fir scribed ¼ S15 BT bears N.30°E., 5.8 ft.  
12" D.Fir scribed ¼ S15 BT bears N.6°W., 12.5 ft.  
6" D.Fir scribed ¼ S22 BT bears South, 24.4 ft.  
12" D.Fir scribed ¼ S22 BT bears S.44°W., 21.0 ft.

Ron Quimby - Crew: R. Heichel & J. Ogden - 2/2020 - C.S. File 65/104-52

-----  
Found - Brass cap (properly mkd)  
10" Fir N.30°E., 5.8 ft. (burnt)  
5/8" I.Rod S.31°W., 8.4 ft.  
5/8" I.Rod S.80°W., 7.5 ft.  
5/8" I.Rod N.18°E., 4.9 ft.  
5/8" I.Rod S.30°E., 8.7 ft.  
All rods have yellow plastic cap stamped "ie engineering". 5' Alum. post alongside.  
Note - Area badly burnt 2019  
Compass decl. 15½°E.