

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7906)

 Set a Laurel post, 4 ins. square, 4 ft. long, 20" in ground, marked T31S R5W S23 on NE., S26 on SE. face, S27 on SW. face and S22 on NW. face. Also two notches on S. and E. angles of the same for the cor. to secs. 22, 23, 26 and 27, from which
 A Laurel 8" dia., bears N.85°E., 30 lks. dist. marked T31S R5W S23 BT.
 A Fir 5" dia., bears S.45°E., 30 lks. dist., marked T31S R5W S26 BT.
 A Laurel 9" dia., bears S.63°W., 57 lks. dist., marked T31S R5W S27 BT.
 A Laurel 9" dia., bears N.80°W., 18 lks. dist., marked T31S R5W S22 BT.

GL0 resurvey by Hans W. Thielsen, under Group #320, Surveyed, Oct./Nov. 1955 - (DCSO records Vol. 28 Page(s) 11788)

 The Sec. cor., determined at record bearing and distance from the original SE. bearing tree:

A Fir 32" dia., bears S.45°E., 30 lks. dist., with marks BT uncovered.

At the corner point

Set an iron post, 36 ins. long, 2 ins. dia., 30 ins. in the ground, with brass cap mkd:

T 31	S R 5 W
S 22	S 23
S 27	S 26
1955	

from which new bearing trees

A White Fir 20" dia., bears N.61°E., 90 lks. dist., marked T31S R5W S23 BT.
 A Red Fir 30" dia., bears S.14°E., 35 lks. dist., marked T31S R5W S26 BT.
 A Red Fir 20" dia., bears S.31°W., 43 lks. dist., marked T31S R5W S27 BT.
 A Red Fir 30" dia., bears N.68°W., 35 lks. dist., marked T31S R5W S22 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Joe Brady - May 1966 - C.S. File 54/25-4

 Found - 1955 Cadastral brass cap.
 Orig. D.Fir S.45°E., 19.8 ft. Had been opened for scribe.
 28" D.Fir S.12°E., 23.1 ft. shows good scar.
 36" D.Fir N.70°W., 23.1 ft. shows good scar.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

19" D.Fir stump S.3½°W., 28.2 ft. opened for scribe.
NE BT gone.
New BTs- 18" D.Fir S.25°W. 30.0 ft scribed T31S R5W S27 CS BT
17" Laurel N.8°W. 21.8 ft scribed T31S R5W S22 CS BT
This corner lies about 60.0 ft. North of small draw, and is
now on E-W cutting line.

Corner Fd. OK, by BLM resurvey by Daniel Berry and Charles
Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO
records Vol. 38 Page(s) 15672)

Survey by Bruce Shaner, L.S. #430 - Jack Wright and Clem
Berlier - June 15, 1992 - C.S. File 63/138-12

Found - 1955 BLM brass cap on 2" galv. I.P. (Set steel fence
post alongside.)
35" D.Fir BT, face badly burned, bears S.40°E.,
(Rec. S.45°E.) 19.8 ft.
32" D.Fir BT, healed blaze, bears S.12°E., (Rec.
S.14°E.) 23.1 ft.
21" D.Fir BT stump, badly burned, bears S.36°W.,
(Rec. S.31°W.) 28.4 ft.
36" D.Fir BT, healed blaze, bears N.68°W., 23.1 ft.
19" D.Fir BT bears S.25°W., 30.4 ft. now gone.
18" Madrone BT, face overgrown, bears N.8°W., 21.8
ft.
New BT - I marked a 12" D.Fir BT, "T31S R5W S27 BT", S.76°W.,
41.8 ft. from corner.
No trees within reasonable distance in NE quadrant (Sec. 23)
as is recent clearcut. Corner is about 650 ft. South of
Mainline Access Road.

Fd. ok by M. Heimbürger, 8/2005 - M148-36

Ron Quimby - Crew: N. Fromdahl & J. Ogden - 9/2019 - C.S.
File 65/104-8

Found - 1955 BLM brass cap (properly mkd)
40" D.Fir S.40°E., 19.8 ft. (face burnt)
36" D.Fir S.12°E., 23.1 ft. good scar
36" D.Fir stump N.68°W., 23.1 ft. Good scar (burnt)
20" D.Fir S.76°W., 41.8 ft. Good scar
T post 0.5 south.
New - 6" D.Fir N.37°E., 26.0 ft. scribed T31S R5W S23 BT
Note - Area burnt badly 2019
Compass decl. 15½°E.