

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 page 7907)

Set a Laurel post, 3 ft. long, 3" square, 18" in ground, marked 1/4 S on W. side for the 1/4 sec. cor., from which
A Laurel 12" dia., bears N.44°E., 18 lks. mkd. 1/4 S BT.
A Laurel 12" dia., bears N.41°W., 31 lks. mkd. 1/4 S BT.

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15672-73)

Point for the 1/4 sec. cor. of secs. 22 and 23, at proportionate distance; there is no remaining evidence at the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap mkd: T 31 S R 5 W

1/4
S 22 | S 23
1973

from which

A sugar Pine 14" dia., bears N.26 1/4°E., 83 1/2 lks. dist., marked 1/4 S23 BT.

A Fir 12" dia., bears N.19°W., 48 1/2 lks. dist., marked 1/4 S22 BT.

Corner is located on spur, slopes W.

Ron Quimby - Crew: N. Fromdahl & J. Ogden - 9/2019 - C.S. File 65/104-7

Found - 1972 BLM brass cap (properly mkd)

23" S.Pine N.26 1/4°E., 55.1 ft.

21" D.Fir (dead) N.19°W., 32.0 ft.

New - 4- 5/8"x30" I.Rod with yellow cap stamped "ie engineering" - rods set 5 ft. N-S-E-W - alum post set by I.Rod

Note - Area burnt badly 2019
Compass decl. 15 1/2°E.