

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7909)

Set a stone, 13x13x12 ins., 10" in ground with 2 notches on East and 4 notches on South angles of same for the cor. to secs. 10, 11, 14 and 15, from which

An Alder 13" dia., bears N.35°E., 27 lks. dist., marked T31S R5W S11 BT.

A Fir 32" dia., bears S.40°E., 29 lks. dist., marked T31S R5W S14 BT.

A Fir 14" dia., bears S.45°W., 27 lks. dist., marked T31S R5W S15 BT.

A Yew 14" dia., bears N.40°W., 28 lks. dist., marked T31S R5W S10 BT.

BLM resurvey by Daniel Berry & Charles Akin under Group #800, Surveyed Sept 1972/June 1973 (DCSO rec Vol. 38 Pg 15677)

Point for the cor. of secs. 10, 11, 14 and 15, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. dia., 22 ins. in the ground, in a mound of stone, 2 ft. base, to top, with brass cap mkd:

T 31 S R 5 W

S 10 | S 11

S 15 | S 14

1973

from which

An Alder 6" dia., bears N.18°E., 64½ lks., mkd. T31S R5W S11 BT.

A Fir 7" dia., bears S.22°E., 78 lks., mkd T31S R5W S14 BT

A Maple 6" dia., bears S.39°W., 32½ lks., mkd. T31S R5W S15 BT.

A Fir 7" dia., bears N.59°W., 76 lks., mkd. T31S R5W S10 BT

Ron Quimby - Crew: R. Heichel & J. Ogden - 1/2020 - C.S. File 65/104-44

Found - BLM brass cap (properly marked)

20" Alder N.18°E., 42.6 ft.

27" Fir N.59°W., 50.2 ft. good scar.

New - ⅝" I.Rod S.4°E., 12.0 ft.

⅝" I.Rod S.62°W., 10.8 ft.

Both have yellow plastic cap stamped "ie engineering". Alum. post alongside.

Note - Area badly burnt 2019

Compass decl. 15½°E.