

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - W.H. Byars, under contract # 456 surveyed July 28, 1882 (DCSO rec. Vol. 19 page 7905)

Set a Laurel post, 3" square, 3 ft. long, 20" in ground, marked ¼ S on N. side for ¼ sec. cor., from which
A Laurel 8" dia., bears North, 49 lks. dist. mkd ¼ S BT.
A Laurel 7" dia., bears S.36°E., 45 lks. dist. mkd ¼ S BT.

GLO resurvey by Hans W. Thielsen, under Group #320, Surveyed, Oct./Nov. 1955 - (DCSO records Vol. 28 Page(s) 11789)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 36 ins. long, 1 in. dia., 30 ins. in the ground, with brass cap mkd:
$$\frac{1}{4} \frac{S \ 26}{S \ 35}$$
1955

from which
A Red Fir 10" dia., bears N.71°E., 25 lks. dist., marked ¼ S26 BT.
A Red Fir 13" dia., bears N.6½°W., 45 lks. dist., marked ¼ S35 BT.

BLM Corrective Resurvey - John Jelley, Lynn Roseberry, Floyd Brooks, Under Group #s 320 and 614, - Surveyed June 1966 through May 1968. (DCSO records Vol. 35 Page(s) 14387)

Point for the ¼ sec. cor. of secs. 26 and 35, at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 36" long, 1" dia., 28" in the ground, with brass cap marked:
$$\frac{1}{4} \frac{S \ 26}{S \ 35}$$
1966
1955

from which
A Fir 9" dia., bears N.32°E., 36 lks. dist. mkd. ¼ S26 BT.
A Fir 25" dia., bears S.14°W. 64 lks. dist. mkd. ¼ S35 BT.
Deposit broken hand axe head at base of iron post.
From this point, the point for the ¼ sec. cor. established in 1955, bears N.18°47'W., 0.525 chs. dist.
Destroyed all marks on the 1955 bearing trees.

Fd. Ok by M. Heimbürger, May 2005 - M146-22