

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Pages 7908-09)

Set a basalt stone, 15x10x8 ins., 10" in ground, marked ¼ on North face for the ¼ sec. cor., from which
A Fir 12" dia., bears N.22°W., 13 lks. marked ¼ S BT.
A Cedar 13" dia., bears S.38°E., 32 lks. marked ¼ S BT.

Victor S. King - Witness: Chester C Jones - For: Bate Lumber Co. Merlin Or. - Feb. 5, 1959 - C.S. File 42/425-3

Found - Basalt stone 15 x 10 x 8 ins. marked ¼ from which Fir snag, burned off nearly flush with the ground, bears N.22°W., 13 lks.
There is no sign of the Cedar BT that should have been on a rock outcrop. This BT very easily could have blown over, burned and left no evidence.

Set 1½" Iron pipe 36" long, set 30" into a mound of stones. It replaces the original stone that is left there as a memorial.

This corner falls at the East base of a solid rock outcrop 10' high and is in an old burn, there are no trees available for bearing trees. I marked two bearing objects, both are 4" +'s chiseled into the rock outcrop:

4" +, N.68°W., 8.5 ft.
4" +, S.50°30'W., 2.2 ft.

DCSO searched for, not found, J. Powell - May 1966

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15674)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. dia., 24 ins. in the ground, with brass cap mkd:

¼ $\frac{S\ 14}{S\ 23}$
T 31 S R 5 W
1973

from which

A Fir 8" dia., bears N.30°E., 43 lks. dist., marked ¼ S14 BT.

A Fir 7" dia., bears S.12°W., 39 lks. dist., marked ¼ S23 BT.

continued next page

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby - Crew: R. Heichel & J. Ogden - 2/2020 - C.S. File 65/104-61

Found - BLM brass cap (properly mkd)
 12" Fir N.30°E., 28.4 ft. badly burnt
 12" Fir S.12°W., 25.7 ft. badly burnt
New - 5/8"x30" I.Rod N.13°W., 4.5 ft.
 5/8"x30" I.Rod N.28°E., 13.6 ft.
 5/8"x30" I.Rod S.36°W., 7.9 ft.
 5/8"x30" I.Rod S.37°E., 7.8 ft.
 All rods have yellow plastic cap stamped "ie
 engineering". 5' Alum. post alongside.
Note - Area badly burnt 2019
 Compass decl. 15½°E.