

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Original - W.H. Byars, under contract # 456 surveyed July 28, 1882 (DCSO rec. Vol. 19 Page 7897)

- 
- Set a basalt stone, 14x12x7 ins., 12" in ground, marked with 3 notches on the South and one notch on the East angles of same for corner to sections 13, 14, 23 and 24, from which
- A Live Oak 14" dia., bears N.50°E., 52 lks. marked T31S R5W S13 BT.
  - A Yew 12" dia., bears S.50°E., 17 lks. dist., marked T31S R5W S24 BT.
  - A Fir 6" dia., bears S.27°W., 28 lks. dist., marked T31S R5W S23 BT.
  - A Fir 15" dia., bears N.48°W., 24 lks. dist., marked T31S R5W S14 BT.

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15661-62)

- 
- The Sec. Cor., monumented with the original unmarked basalt stone, 14 x 12 x 7 ins., firmly set 10" in the ground, from which the remains of the original bearing tree:
- A Live Oak 22" dia., bears N.50°E., 49 lks. dist., no marks visible. (Rec. 52 lks.)
  - A Yew 15" dia., bears S.50°E., 17 lks. dist., with scribe marks X BT visible on bark.
  - A Fir 12" dia., bears S.27°W., 8 lks. dist., with scribe mark T visible on opened blaze.
  - A Fir stump, 24" dia., bears N.48°W., 24 lks. dist., no marks visible.

At the corner point  
 Set an iron post, 28 ins. long, 2½ in. diam., 24 ins. in the ground, with brass cap mkd:

T	31	S	R	5	W
	S	14		S	13
	S	23		S	24
				1973	

- from which new bearing trees:
- A Fir 10" dia., bears N.20°E., 23 lks. dist., mkd. T31S R5W S13 BT.
  - A Fir 8" dia., bears S.51¼°E., 44½ lks. dist., mkd. T31S R5W S24 BT.
  - A Fir 14" dia., bears S.64½°W., 8 lks. dist., mkd. T31S R5W S23 BT.
  - A Fir 9" dia., bears N.51°W., 33½ lks. dist., mkd. T31S R5W S14 BT.
- Deposit corner stone alongside iron post.

Cont. next page

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Greg Lang, for Silver Butte Timber Co. Feb. 1996 - M 127-73  
-----  
Found Brass cap and BT's of record.  
Note - Yew in SE quadrant is gone.  
Record Fir S.27°W. 8 lks. is a snag.

Fd. & used on BLM dependent resurvey by Bryan S. Seibold,  
Cadastral Surveyor, under Group #1861, surveyed Sept. 3,  
1997 - (DCSO records Vol. 53 Page(s) 20265)

Ron Quimby - Crew: R. Heichel & J. Ogden - 2/2020 - C.S.  
File 65/104-55  
-----  
Found - BLM brass cap (properly mkd)  
22" Oak stump N.50°E., 32.3 ft. (no marks)  
14" Fir N.20°E., 15.2 ft. vis. scar.  
New - 5/8"x30" I.Rod N.81°W., 5.5 ft.  
5/8"x30" I.Rod S.52°E., 5.6 ft.  
5/8"x30" I.Rod S.30°W., 4.3 ft.  
All rods have yellow plastic cap stamped "ie  
engineering". 5' Alum. post alongside.  
Note - Area badly burnt 2019  
Compass decl. 15½°E