

PRIMARY CORNER DESCRIPTION W. Sec. Cor. for 30 & 31 only, T31-4

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Wm. M. Bushey, under Contract #620 dated June 17, 1893 (DCSO records, Vol. 18 Page 7854)

 At point of intersection, I set a stone, 14x10x6 ins., 10" in the ground, for closing cor. to secs.30 and 31, marked C C on E face, with 5 notches on N and 1 notch on S faces; from which

- A Fir 36" dia., bears N.74°E., 73 lks. dist., marked T31S R4W S30 BT.
- A Fir 20" dia., bears S.81 3/4°E., 61 lks. dist., marked T31S R4W S31 BT.
- A Fir 33" dia., bears S.39 1/4°W., 29 lks. dist., marked T31S R4W C C S30 and 31 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Joe Brady - March 1966 - C.S. File 54/20-48

 Found - 36" Fir, now dead snag, N.74°E., 48.2 ft. shows scar
 20" Fir now blown down, S.81 3/4°E., 40.3 ft.
 33" Fir now stump, S.39 1/4°W., 19.1 ft. scribe visible "S3".

No trace of stone at corner.

Set Brass cap at cor. mkd: County Surveyors Office

R	T	31	S	R
5		S	30	4
W		S	31	W
		S	25	
		S	36	
			1966	

New BT - 3" Fir N.79 1/2°E., 19.4 ft. scribed S30 BT.

Reblazed and rescribed:

39" Fir stump S.39 1/4°W., 19.1 ft. scribed "T31S R5W S25 CS BT".

This corner lies in large cut unit.

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15643-44)

 The original closing corner, perpetuated by Powell in 1966, monumented with an iron post, 1 1/2" dia., firmly set, protruding 8" above ground, with brass cap mkd: COUNTY SURVEYORS OFFICE

T	31	S	R	4	W
		S	25		S
					S
					30
					31
		R	5	W	
					1966

(Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 700204

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 and 31 only, T31-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

from which the remains of the original bearing trees:
A Fir snag 40" dia., bears N.74°E., 73 lks. dist. with
healed blaze.
A root hole, bears S.81 3/4°E., 61 lks. dist., with a down
fir alongside, 30" dia., no marks visible.
A Fir stump 40" dia., bears S.39 1/4°W., 29 lks. dist., with
scribe marks S 3 visible on opened blaze.
and bearing trees mkd. by Powell:
A Fir 5" dia., bears N.80°E., 29 lks. dist., with healed
blaze.
A Fir 7" dia., bears N.20°E., 26 lks. dist., with scribe
marks BT visible on partially healed blaze.

BLM resurvey by Wayne Rogers, Rick McMullen and Lance Bishop
under Group #1217. Surveyed, Sept. 1984/April 1986 (DCSO
records Vol. 47 Page 18155 Page(s))

True point for the closing corner of secs.30 and 31.
Set a stainless steel post, 28" long, 2 1/2 ins. diam., 22" in
the ground, with brass cap mkd: T 31 S
 R 5 W | R 4 W
 S 25 | S 30 C C
 S 31 1985

from which
A Fir 7" dia., bears N.30°E., 21 1/2 lks. dist., mkd. T31S
R4W S30 CC BT.
A Fir 10" dia., bears S.46 1/2°E., 19 lks. dist., mkd. T31S
R4W S 31 CC BT.

The corner is located on steep S. slope.

From this point, the original closing cor. of secs. 30 and
31, bears S.89°54'W., 0.065 chs. dist., perpetuated and
recorded by Powell in 1966, monumented with an iron post 1 1/4"
dia., firmly set, projecting 12" above ground, with brass cap
mkd. COUNTY SURVEYORS OFFICE T31S R4W R5W S30 S31 S25 1966,
from which the remains of an original bearing tree:

A decayed Fir stump, 30" dia., bears S.39 1/4°W., 29 lks.
dist., rescribed by Powell with scribe marks BT
visible.

and bearing trees mkd. by Powell:

A Fir 14" dia., bears N.20°E., 26 lks. dist., with healed
blaze.
A Double Fir 9" dia., bears N.80°E., 29 lks. dist., with
healed double blaze.