

PRIMARY CORNER DESCRIPTION W 1/4 Cor. for Sec. 13 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Original - Butler Ives and Geo. Hyde under Contract #39 dated Jan. 4, 1854 (DCSO records Vol. 18 Page(s) 7778)</p> <p>-----</p> <p>Set ¼ sec. post, on W point of a ridge, from which A Fir 8" dia., bears S.73°W., 15 lks. A Laurel 10" dia., bears S.71°E., 41 lks.</p>						
<p>GLO survey by Wm. M. Bushey, under Contract #620 dated June 17, 1893 (DCSO records Vol. 19 Page(s) 7867)</p> <p>-----</p> <p>Set temp. post. The ¼ sec. cor. is gone. I find 1 witness tree at cor. point. Set a stone, 14x12x9 ins. 10" in the ground, for ¼ sec. cor. marked ¼ on W face; from which A Fir 8" dia., (12" now) bears S.73°W., 15 lks. dist., marked ¼ S BT. Fire has destroyed the Laurel in Sec. 18. I therefore mark A Laurel 7" dia., which bears N.34°E., 29 lks. dist., ¼ S BT.</p>						
<p>BLM resurvey by Berry and Akin, under Group 800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15647-48)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of sec. 13 only, determined by the method of irregular boundaries, there is no remaining evidence of the original corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:</p> <table><tr><td>¼ S 13</td><td> </td></tr><tr><td>T 31 S</td><td> </td></tr><tr><td>R 5 W</td><td> </td></tr></table> <p>1973</p> <p>from which A Fir 8" dia., bears S.20°W., 46½ lks. dist., marked ¼ S13 BT. A Fir 6" dia., bears N.81½°W., 54½ lks. dist., marked ¼ S13 BT.</p>	¼ S 13		T 31 S		R 5 W	
¼ S 13						
T 31 S						
R 5 W						
<p>Fd. OK by Kris DeGroot, 3/2005 - M 146-19</p>						
<p>1</p>						