

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8011)

Set Laurel post, 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Laurel 8" dia., bears N.18°E., 17 lks. dist. mkd. 1/4 S BT
A Laurel 10" dia., bears South, 18 lks. dist. mkd. 1/4 S BT

Douglas Co. Surveyors Office - Milo Godfrey, Deputy - Mike Stone, crew - June 1964 - C.S. File 52/25-19

Found - Madrone, now 21" dia., N.18°E., 11.2 ft., previously opened, good scribing visible "1/4S"
Portion of rotten Laurel on ground in general location of South BT, impossible to determine where it stood.

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 6 W
1/4 S 8
S 17
1964

New BTs - 8" D.Fir S.74°E., 9.0 ft. mkd. 1/4 S17 CS BT.
8" D.Fir N.83°W., 7.0 ft. mkd. 1/4 S 8 CS BT.

Jerry Estabrook - Bruce Webster - 9/19/03 - C.S. 65/48-29

Found - 2 1/2" brass cap on 1" iron pipe 12" above grade.
Madrone 21" diameter 15+/- foot tall snag, bears N.18°E., 11.2 ft with new growth where face should be. New tag.

New - A D.Fir 10" dia bears N.77°E. 22.1 ft face scribed "1/4 S8 BT" with spike at side center & tagged.
A D.Fir 10" dia bears N.11°E, 26.2 ft face scribed "1/4 S8 BT" with spike at side center & tagged.
A 5/8"x30" iron rod with a 1 1/2" aluminum cap marked "BO over 1" set 25" deep, bears S.47°E., 6.3 ft
A 5/8"x30" iron rod with a 1 1/2" aluminum cap marked "BO over 2" set 25" deep, bears S.44°W, 7.8 ft.

Note - A lightweight steel fence post was set near each, the corner, B01 and B02 . Corner falls approx 1 chain north of a shallow east flowing draw on 50-60% S-SE facing slope. Dec. 19°E.

Mark Heimbürger - Crew: Bartt Heichel & Anthony Welch - 1/2018 - C.S. File 65/101-42

Found - 2 1/2" brass cap on 1" iron pipe from which a:
continued next page

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION _____

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

21" Madrone snag bears N.18°E., 11.2'
10" (now 13") D. fir with healed face bears N.77°E.,
22.1' to spike @ center.
10" (now 11") D. fir with healed face bears N.11°E.,
26.2' to spike @ center.
5/8" iron rod with aluminum cap marked "B01" bears
N.47°W., 6.3'
5/8" iron rod with aluminum cap marked "B02" bears
N.44°E., 7.7'
Note - Declination 15°