

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7991)

Set Cedar post, 4 ft. long, 4" sq., 24" in the ground, for cor. to secs. 28, 29., 32 and 33, mkd. T31S R6W S28 on NE.; S33 on SE.; S32 on SW.; and S29 on NW.; faces with 1 notch on S. and 4 notches on E. edges, from which
A Fir 30" dia., bears N.15°E., 22 lks. dist. mkd. T31S R6W S28 BT.
A Fir 16" dia., bears S.51°E., 49 lks. dist. mkd. T31S R6W S33 BT.
A Fir 16" dia., bears S.76°W., 45 lks. dist. mkd. T31S R6W S32 BT.
A Fir 28" dia., bears N.65°W., 20 lks. dist. mkd. T31S R6W S29 BT.

Survey by R. H. Gee - For: R.J. Henrickson and F. McCornack - Dec. 29-30, 1954 - C.S. File 41/338-1

Found - Orig. corner post standing and in place. Replaced corner with a 3/4" Iron pipe from which bears:
Fir 38", N.15°E., 14.5 ft. scribed S28 in bark (Orig. BT)
Fir 32", N.65°W., 13.2 ft. scribed S29 in bark (Orig. BT)
Fir 10", S.44°E., 16.5 ft. scribed S33 T31S R6W W.M. BT.
(This is new BT.)
Fir 10", S.28°W., 23.2 ft. scribed S32 T31S R6W W.M. (This is new BT)

Survey by Clifford M. Brydon - For: Roseburg Lumber Co. - Feb. 14, 1957 - C.S. File 42/250-1

This corner destroyed by road building, all BTs destroyed. Reset corner from references set when corner previously renewed by R.H. Gee.
1/2" x 3 ft. Iron pipe at corner, from which new witness trees:
Fir 4", S.77½°E., 74.8 ft.
Fir 6", S.42½°W., 66.1 ft.
Fir 4", N.38°E., 36.5 ft.
Fir 4", N.4°W., 76.4 ft.
scribed R.E. 3987 B.T.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone, crew - Oct. 1966 - C.S. File 54/31-21

Found - 1/2" Iron pipe, torn out of ground.
4" now 6" W.Fir S.77½°E., 74.8 ft. scribe marks visible. (Cont. Next Page)

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

4" now 7" D.Fir, N.38°E., 36.5 ft. shows good scar.
4" now 6" D.Fir N.4°W., 76.4 ft. scribe marks visible.
6" Fir, blown down, S.42½°W., 66.1 ft.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 6 W
S 29 | S 28
S 32 | S 33
1966
New BT - 40" D.Fir N.84°W., 89.4 ft scribed T31S R6W S29 CSBT
This corner lies on South edge of road. Squared stake at brass cap.

Douglas Co. Surveyors Office - R. B. Kimberling, Deputy -
P.L. Earle, crew - Aug. 1, 1977 - C.S. File 59/38-10

Found - A 1" x 36" I.P. with brass cap laying beside road
and properly marked, 1966 DCS0.
A W.Fir 4" now 7", bears S.77½°E., 74.8 ft. with
well healed blaze.
A D.Fir 4" now 8", bears N.38°E., 36.5 ft. with well
healed blaze.
A D.Fir 4" now 7", bears N.4°W., 77.5 ft. (Rec. 76.4
ft.) with visible scribing in partially healed
blaze.
A 40" Fir stump, bears N.81¼°W., 98.2 ft. (Rec.
N.84°W., 89.4 ft.) (BT tag rec. N.84°W., 98.2
ft.) marked "T31S R6W S29 CS BT" in partially
healed blaze.
Reset Brass cap stamped to read "T31S R6W S29 S28 S32 S33
Reset 1977 1966."
No new accessories.
Corner is on South edge of gravel road.

Mark Smalley - For: Kenneth & Hallie Ford - Jan 1995 - M121-57

Mon. Fd. - 1977 Co. Brass cap & Iron pipe
BT's Fd. - 10" fir, N.4°W 76.4' healed
14" fir, N.38°E. 36.5' healed
10" fir, S.77½°E. 74.8' healed
New BT's - 8" fir, S.12°W. 62.8' "S 33 BT"

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 3/27/25 - C.S. File 67/60-18

Found - DCS0 brass cap on iron pipe.
12"x2 ft fir stump N.4°W. 76.4 ft.
Continued next page

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

14"x2 ft fir stump N.38°E. 36.5 ft
10"x6 ft fir stump S.12°W. 62.8 ft

COUNTY SURVEYORS

OFFICE

T31S R6W

S29|S28

S32|S33

1966 RESET 1977

Note - Add 3½" mag nail top center of 2 short stumps.
Add 3½" mag nail right side center of 6 ft stump.

New - ⅝"x30" I. Rod with DCS0 plastic cap S.80°E.
53.2 ft.

Compass decl. 14½°E.

OCRS COORDINATE SYSTEM

COTTAGE GROVE-CANYONVILLE ZONE

N 2741.191 E 138930.969