

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7990)

Set Fir post 3 ft. long, 3" sq., 18" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Fir 10" dia., bears S.40°E., 49 lks. mkd. ¼ S BT
A Fir 16" dia., bears N.68°W., 20 lks. mkd. ¼ S BT

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey, Clete Putnam, crew - May 23, 1960 - C.S. File 52/25-1

Found - Rotted Fir stump, now 23", N.58°W., (rec. N.68°W., 13.2 ft.) showing bark scribe "BT"
Fir stump, now 25", S.40°E., 32.3 ft. Showing bark scribe "BT"

Set Iron post with brass cap mkd: County Surveyors Office
T 31 S R 6 W
¼ S4 | S3
1960

Blaze and scribe new trees:
10" Red Fir S.19°W., 35.9 ft. mkd. "¼S S4 CS BT"
20" Red Fir S.39°E., 35.2 ft. mkd. "¼S S3 CS BT"

Fd. OK, George Grubb, Aug. 1981, M 88-67

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1875, surveyed May 1998 - July 1998 - (DCSO records Vol. 53 Page(s) 20578-9)

The ¼ sec. cor. of secs. 3 & 4, perpetuated by Byron, Deputy in 1960; monumented with an iron post, 1½" dia., firmly set, projecting 12" above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE
T 31 S R 6 W
¼ S 4 | S 3
1960

from which the remains of the original bearing trees
A sawed fir stump, 25" dia., bears S.37°E., 45½ lks., with fragmentary scribe marks visible on the bark. (Record, S.40°E., 49 lks.)

A partially decayed fir stump, size indeterminate, bears N.60°W., 20 lks., with no marks visible. (Record, N.68°W.)

and the remains of bearing trees mkd. by Byron
A fir, 23" dia., bears S.39°E., 52 lks., with healed blaze.

continued next page

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed fir stump, 23" dia., bears S.17°W., 54½ lks., with
no mks. visible.
and a new bearing tree
A fir, 6" dia., bears S.43½°W., 49 lks., mkd. 1/4 S4 BT.

Fd. OK by K. DeGroot, Jan. 2004 - M137-77