

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7975-76)

Set Fir post, 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 10, 11, 14 and 15, mkd. T31S R6W S11 on NE.; S14 on SE.; S15 on SW.; and S10 on NW. faces, with 2 notches on E. and 4 notches on S. edges, from which
A Fir 12" dia., bears N.60°E., 18 lks. dist. mkd. T31S R6W S11 BT.
A Fir 12" dia., bears S.21°E., 12 lks. dist. mkd. T31S R6W S14 BT.
A Chinkapin 10" dia., bears S.78°W., 30 lks. dist. mkd. T31S R6W S15 BT.
A Fir 14" dia., bears N.30°W., 30 lks. dist. mkd. T31S R6W S10 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone, crew - Sept/Oct. 1966 - C.S. File 54/31-9

Found - Post scribed S10, S11, S14, S15.
12" now 15" D.Fir N.60°E., 11.9 ft., shows good scar.
14" D.Fir, now stump, N.30°W., 19.8 ft., opened log for scribing "BT", scribing very high, not on stump.

No trace of SE nor SE trees.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 6 W
S 10 | S 11
S 15 | S 14
1966

New BTs -22" D.Fir N.51°W., 64.0 ft. mkd. T31S R6W S10 CS BT.
25" D.Fir S.8°W., 39.6 ft. mkd. T31S R6W S15 CS BT.
5" D.Fir S.57°E., 45.0 ft. mkd. T31S R6W S14 CS BT.
This corner lies in corner of cut unit. No trees in SE quad.

1966 Brass cap, 2 orig. BTs and 3 DCSO BTs, found and used in BLM Survey by Jelley and Rogers, under Group #1042, surveyed Oct. 1980/Oct. 1981 (DCSO records, Vol. 45 Pages 17295-96)

Gregg Neitsch - For: Silver Butte Tbr Co. - 2/2024 - M183-41

Found - 1" I.D. GIP with a 2½" BC stamped "COUNTY SURVEYORS OFFICE T31S R6W S10 S11 S15 S14 1966", 20" above ground, from which bears:
26" DF stump, rotted, N.56½°E., 11.9' (N.60°E., 11.9')

continued next page

