

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7977)

-----  
Set Oak post, 4 ft. long, 4" sq., 24" in the ground, for cor. to secs. 2, 3, 10 and 11, mkd. T31S R6W S2 on NE.; S11 on SE.; S10 on SW.; and S3 on NW. faces, with 2 notches on E. and 5 notches on S. edges, from which  
A Laurel 6" dia., bears N.60°E., 67 lks mkd 31S R6W S2 BT  
A Laurel 20" dia bears S.76°E., 74 lks mkd T31S R6W S11 BT  
A Pine 30" dia. bears S.30°W., 83 lks mkd. T31S R6W S10 BT  
A Pine 36" dia., bears N.33°W., 60 lks mkd. T31S R6W S3 BT

John Markham, Jr. - For: Logsdon Bros. - Wit: George Vaughn, Bill Vaughn - Dec. 1949/Jan. 1950 - C.S. File 40/233

-----  
Determined from remains of O.B.T.s:  
27" Laurel bears S.80°E., 46½ ft. dist., scribe legible.  
16" Laurel bears N.60°E., 42½ ft. Rescribed this O.B.T., S2 2880 BT.  
Dead Pine snag, N.28°W., 41.0 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone, crew - Oct. 1966 - C.S. File 54/31-14

-----  
Found - 1" Iron pipe, not recorded.  
Pine snag N.28°W., 41.0 ft.  
Orig. 27" now 30" Laurel S.80°E., 46.5 ft., tree open, scribe visible, rotten face.  
Orig. 16" now 20" Laurel N.60°E., 42.5 ft. Tree had been opened, no orig. scribe visible. Rescribe "BT" visible.

Set Brass cap at cor. mkd: County Surveyors Office

T	31	S	R	6	W
S	3	S	2		
S	10	S	11		
1966					

New BTs -16" D.Fir S.5°E., 17.6 ft. mkd. T31S R6W S11 CS BT.  
7" D.Fir N.54°E., 13.5 ft. mkd. T31S R6W S2 CS BT.  
9" D.Fir N.34°W., 26.6 ft. mkd. T31S R6W S3 CS BT.  
7" D.Fir S.45°W., 23.0 ft. mkd. T31S R6W S10 CS BT.

Raymond Brown, L.S. # 2391 - For: Silver Butte Timber, City of Riddle, Nancy Grace & Daniel Johnson - 4/1995 - M 119-61

-----  
Found brass cap, per 1966 renewal, with proper marks. All BTs are dead from burn, No suitable trees within limits.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause;  
Sept. 25, 1996 - C.S. File 65/9-17

-----  
Found - 2½" dia. brass cap on a 1½" O.D. iron pipe,  
protrudes 14" above ground. (1966, DCSO)  
- 1" I.D. iron pipe protrudes 8" above ground is found  
along north side of BC/IP. (source unknown)

Accessories Found -

6" now 21" dia. almost dead Madrone with a previously  
opened blaze, no scribing visible, bears N.60°E., 42.5  
ft. (agrees with rec.) O.B.T.

20" now 32" dia. dead Madrone with a previously opened  
blaze, no scribing visible, bears S.80°E., 45.3 ft.  
(rec. S.80°E., 46.5 ft. per renewals) O.B.T.

7" now 18" dia. down D.Fir with a fully healed double  
blaze, bears N.54°E., 13.5 ft. to root hole (agrees  
with rec.) 1966

16" now 18" dia. 5 ft. high D.Fir stump with a fully  
healed double blaze, bears S.5°E., 17.6 ft. (agrees  
with rec.) 1966

7" now 12" dia. 3 ft. high D.Fir stump with a fully healed  
double blaze, bears S.45°W., 23.0 ft. (agrees with  
rec.) 1966

9" now 22" dia. 45 ft. high D.Fir snag with a fully healed  
double blaze, bears N.34°W., 26.6 ft. (agrees with  
rec.) 1966

New Accessories -

7" dia. Madrone, double blazed and scribed "T31S R6W S3 CS  
BT" bears N.4°W., 34.6 ft.

3" dia. Madrone, double blazed and scribed "X BT" bears  
S.66°W., 16.9 ft.

Fd. Ok by K. DeGroot, May 2004 - M146-5

BLM dependent resurvey by Jeffrey O. Covington, Cadastral  
Surveyor, under Group No. 2891, surveyed Oct 2017/March 2018-  
(DCSO records Vol. 59 Page 23798-9 & Plat T31-6 2020-1)

-----  
The cor. of secs. 2, 3, 10, & 11, perpetuated by Markham Jr,  
in December 1949; subsequently perpetuated by Douglas County  
Surveyors Office, in 1966; further perpetuated by Douglas  
County Surveyors Office, in 1996; monumented with an iron  
post, 1¼" dia., firmly set, projecting 8" above ground  
(alongside of which is an iron pipe, 1½" dia. firmly set,  
projecting 6" above ground), with a brass cap (properly) mkd.  
from which the remains of an original bearing tree

A hollowed madrone, 18" dia., bears N.60°E., 44.2 ft.,  
with no marks visible on open blaze. Cont. Next pg

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of the BTs mkd. by Douglas Co Surveyors Office in 1966  
A roothole bears N.55°E., 13.4 ft., alongside of which is  
a down decayed fir, 11" dia., with reverse scribe marks  
T31S R6W visible on inside of the healed blaze.

A decayed fir snag, 18" dia., bears S.6°E., 17.2 ft., axe  
marks visible.

A sawed decayed fir stump, 12" dia., bears S.44¾°W., 22.4  
ft., with a healed blaze.

A decayed fir snag, 22" dia., bears N.31½°W., 26 6 ft.,  
with a healed blaze.

and the remains of the BTs mkd by Douglas County Surveyors Office in 1996  
A sawed madrone stump, 5" dia., bears S.65¾°W., 162 ft.,  
with illegible scribe marks visible on partially healed  
blaze.

A madrone, 11" dia., bears N.3¼°W., 35.2 ft., with a  
partially healed double blaze.

and new bearing trees

A fir, 9" dia., bears S.29¾°E., 20.6 ft., T31S R6W S11 BT.

A madrone, 5" dia., bears S.67½°W., 16.2 ft., mkd. X BT on  
bark.

NAD 1983 (2011)

Latitude 42°53'52.31"N

Longitude 123°23'17.20"W