

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; & 12, T31-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8033)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground, marked 1/4 S. on W. side for the 1/4 sec. cor., from which
A Fir 42" dia., bears S.75°E., 34 lks. dist., mkd. 1/4 S BT
A Fir 14" dia., bears S.54°W., 54 lks. dist., mkd. 1/4 S BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Cliff Stone - Dec. 1966 - C.S. File 54/36-68

Found - 42" now 62" D.Fir, S.75°E., 22.4 ft., faint scribe visible.

No trace of SW. BT.

Set Brass cap at cor. mkd: County Surveyors Office
R T 31 S R
8 1/4 S12 | S 7 7
W 1966 W

New BTs -8" W.Fir N.89 1/2°E., 53.2 ft. mkd. 1/4 S7 CS BT.
10" W.Fir N.85°W., 32.9 ft. mkd. 1/4 S12 CS BT.

David Edwards - For: Seneca Jones Timber & Roseburg Resources - Nov. 2017 - M173-76

Found - Brass cap

All previous BTs are burned away.

No line trees available due to fire.

Set - 6' steel posts 2 ft north, 2 ft south, and 2 ft. S.88°W.