

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8080)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground, mkd. ¼ S. on N. side for the ¼ sec. cor., from which
A Fir 40" dia., bears S.8°W., 18 lks. dist. mkd. ¼ S BT.
A Fir 12" dia., bears N.6°E., 65 lks. dist. mkd. ¼ S BT.

Survey by G. Robert Lecklider - For: C & D Lumber Co. - June 1962 - M 23-68

Found no evidence of original corner.
Set 1" Iron pipe for corner by proportionate measurement. from which
28" Fir N.6°E., 4.2 ft. mkd. ¼ S7 RE 4079 BT.
42" Fir S.43°W., 14.2 ft. mkd. ¼ S18 RE 4079 BT.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - July 17, 1978 - C.S. File 58/175-1

Found - Iron pipe which had been pulled out of the ground.
42" D.Fir bears N.40°E., 14.0 ft.
30" D.Fir bears N.12°E., 14.8 ft., now a stump.
Set 5/8" x 30" Iron rod.
Scribed- 9" D.Fir bears S.9°W., 46.6 ft.

Ron Quimby - Ryan Palmer, Party chief - 3/2011 - C.S 65/72-10

Found - 5/8" I.Rod
44" Fir S.43°W., 14.2 ft. vis. scribes.
30" D.Fir stump N.12°E., 14.8 ft. (Tin on top)
New - 12" D.Fir N.68°E., 13.1 ft. scribed ¼ S7 BT.
50" Cedar S.39°E., 23.3 ft. scribed ¼ S19 BT.
Note - Corner is approx. 400' east of main N-S ridge & road on gentle North slope.