

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8078)

Set a Fir post, 3 ft. long, 3" sq., 18" in the ground, mkd. ¼ S. on NW. side for the ¼ sec. cor., from which

A S.Pine 12" dia., bears N.50°E., 12 lks. dist. mkd. ¼ S BT.

A Laurel 12" dia., bears West, 20 lks. dist. mkd. ¼ S BT.

Survey by G. Robert Lecklider - For: C & D Lumber Co. - June 1962 - M 23-68

Found No evidence of original govt. corner. Controlled departure by straight line between sec. cors. Controlled latitude by call on R.R. 8.5 chs. North of corner.

Set 1" Pipe with cap for corner, from which

16" Fir S.32°E., 19.5 ft. mkd. ¼ S17 RE 4079 BT.

22" Fir S.1°W., 36.0 ft. mkd. ¼ S18 RE 4079 BT.

David Edwards - Crew: Brant Miller & Eric Sprinkle - 12/13/2017 - C.S. File 65/99-35

Found - Lecklider's pipe/cap not found.

Lecklider's BTs found:

A 19" dia. Fir with 2 healed blazes bears S.32°E., 19.5 ft.

A 26" dia. Fir with partial bark scribing visible bears S.1°W., 36.0 ft.

Set - 5/8"x30" steel rebar with 2½" dia. aluminum cap marked per the 2009 BLM manual and marked "L.S. 2339" and "2017" using the record bearings and distances from M 23-68. (from the found bearing trees).

New - A six foot steel post is set 2 feet North. Compass decl. 15°E.