

PRIMARY CORNER DESCRIPTION Sec Cor for 7, 8, 17 and 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8078)

Set a Fir post 4 ft. long, 4" sq., 20" in the ground mkd. T31S R7W S8 on NE. face; S17 on SE. face; S18 on SW. face; and S7 on the NW. face. Also 4 notches on the S. and 5 on the E. angles of same for the cor. to secs. 7, 8, 17 and 18, from which

- A Fir 14" dia., bears N.13°E., 26 lks. dist. mkd. T31S R7W S8 BT.
- A Fir 12" dia., bears S.46°E., 18 lks. dist. mkd. T31S R7W S17 BT.
- A Fir 15" dia., bears S.89°W., 48 lks. dist. mkd. T31S R7W S18 BT.
- A Fir 16" dia., bears N.44°W., 37 lks. dist. mkd. T31S R7W S7 BT.

George Wenderoth - For: C & D Lumber Co. - During the fall of 1961 - C.S. File 52/29-1

(At the request from Fred M. Darby, County Surveyor, Wenderoth filed notes for this corner. Letter in C.S. File) "Here are the notes on the corner as set by me. You will notice that the bearing of original BTs do not jibe with original notes")

- 40" Fir N.41°50'W., 23.7 ft. OBT.
- 40" Fir S.82°06'W., 27.8 ft. OBT.
- 36" Fir S.44°45'E., 11.4 ft. OBT.
- 18" Fir N.53°34'E., 11.4 ft.

Survey by G. Robert Lecklider - For: C & D Lumber Co. - June 1962 - M 23-68

Found four BTs, scribe or rescribed by Wenderoth in 1961. BTs do not fit orig. Govt. field notes.

- 1" iron pipe set for corner, from which
- 20" Fir N.55°E., 12.0 ft.
 - 30" Fir S.44°E., 12.4 ft.
 - 34" Fir N.42°W., 25.0 ft.
 - 34" Fir S.82°W., 29.2 ft.

Douglas Co. Surveyors Office - Clell Goodwin; Gary Langlitz; Vic Cangie, Lenora Ladig, crew -Oct. 2, 1975 - C.S. File 57/36-15

Found - 1" Iron pipe as described by Lecklider.
(Cont. Next Page)

