TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8080-81

Set a Laurel post 3 ft. long, 4" sq., 18" in the ground for the ¼ sec. cor. marked ¼ S. on N. side, from which
A Laurel 6" dia., bears S.85°E., 27 lks. mkd. ¼ S BT.
A Cedar 14" dia., bears N.85°W., 58 lks. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John Powell and crew - June 25, 1969 - C.S. File 54/36-22

Looked for, not found.
Found old N-S blazed line. Also, very possible BTs. Old axe work, nothing definite because of fire and rot.

BLM resurvey by James L. White, Cadastral Surveyor, under Group #1239, surveyed Jan/Feb. 1985 - (DCSO records Vol. 47 Page(s) 18101)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an alum. post, 28" long, 2 1/2" dia., 23" in the ground, with alum. cap mkd: T 31 S R 7 W

¼
S 7|S 8
1985

from which
A Fir 6" dia., bears N.41½°E., 36 lks. dist. mkd. ¼ S8 BT.
A Fir 5" dia., bears N.73½°W., 16½ lks. dist. mkd. ¼ S7 BT