

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8067)

-----  
Set a Laurel post 40" long, 20" in the ground, 4" sq., marked 1/4 S. on W. side for the 1/4 sec. cor., from which  
A Laurel 7" dia., bears S.50°W., 42 lks. dist. mkd. 1/4 S BT  
A Fir 16" dia., bears N.6°E., 9 lks. dist. mkd. 1/4 S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - John Powell, Wm Stoffel, crew - Oct 31, 1962 - C.S. File 49/109-11

-----  
Found - Orig. 16" now 36" Fir snag, N.6°E., 5.9 ft., shows good bark scribing "1/4BT".  
Stump hole that checks for SW. BT.

Set Brass cap at cor. mkd: County Surveyors Office  
T 31 S R 7 W  
1/4 S17 | S16  
1962

New BTs- 7" R.Fir bears S.47°W., 26.5 ft. scribed 1/4 S17 CSBT  
8" Live Oak bears S.78°E., 17.0 ft. scribed 1/4 S16 CS BT.

DCSO-GIS Corner visitation - 2/2/2004 - Typed: 2/10/2011 - C.S. File 67/33-1

-----  
Monument - 1 1/4" IP/BC Comment - rehab