

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8065)

Set a Fir post 40" long, 4" sq., 18" in the ground marked ¼ S. on N. side, for the ¼ sec. cor., from which
A Pine 30" dia., bears N.35°E., 21 lks. dist. mkd. ¼ S BT
A Pine 34" dia., bears S.27°W., 62 lks. dist. mkd. ¼ S BT

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531 - Surveyed Oct 1963/June 1964 - (DCSO records Vol. 33 Page(s) 13640)

The ¼ sec. cor., determined at record bearing and distance from the remains of the original bearing trees:

A down Pine 30" dia., bears N.35°E., 21 lks. dist., with no marks remaining.

A Pine snag 36" dia., bears S.27°W., 62 lks. dist., with no marks remaining.

The corner falls on an old blazed line which extends East and West.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 7 W

¼ S 21
S 28
1964

from which new bearing trees:

A Fir 10" dia., bears N.75°E., 10½ lks. dist. mkd. ¼ S21 BT.

A Fir 10" dia., bears S.43 3/4°W., 11½ lks. dist. mkd. ¼ S28 BT.