

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8060)

Set a Fir post 4 ft. long, 4" sq., 24" in the ground marked T31S R7W S10 on NE. face; S15 on SE. face; S16 on SW. face; and S9 on NW. face; also 4 notches on S. and 3 notches on E. angles of same for the cor. to secs 9, 10, 15 & 16 from which
A Pine 16" dia., bears N.32°E., 24 lks mkd T31S R7W S10 BT
A Pine 32" dia., bears S.55°E., 13 lks mkd T31S R7W S15 BT
A Pine 16" dia., bears S.72°W., 16 lks mkd T31S R7W S16 BT
A Pine 22" dia., bears N.34°W., 30 lks mkd. T31S R7W S9 BT

BLM resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #834, surveyed April/June 1974 - (DCSO records Vol. 39 Page(s) 15741-42)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 7 W
S 9 | S 10
S 16 | S 15
1974

from which

A Fir 8" dia., bears N.15°E., 38 lks mkd. T31S R7W S10 BT.
A Fir 8" dia., bears S.38½°E., 21 lks mkd. T31SR7W S15 BT.
A Fir 10" dia., bears S.8°W., 33 lks mkd. T31S R7W S16 BT.
A Fir 12" dia., bears N.12°W., 50 lks mkd. T31S R7W S9 BT.

DCSO-GIS Corner visitation - 2/2/2004 - Typed: 2/10/2011 - C.S. File 67/33-1

Monument - 2½" IP/BC

Ron Quimby - Crew: R. Olsen & R. Heichel - 12/2017 - C.S. File 65/99-36

Found - BLM brass cap (properly mkd)

22" Fir N.15°E., 25.1 ft. good scar

14" Fir S.38°E., 13.9 ft. good scar

23" Fir N.12°W., 33.0 ft. good scar

16" Fir stump S.8°W., 21.8 ft. (burnt out)

New - 5/8" I.Rod with yellow plastic cap ie engineering S.8°W., 19.8 ft. post alongside.

Note - Area badly burnt 9/2017
Compass decl. 15½°E.