

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8057)

Set Cedar post 4" sq., 40" long, 20" in the ground, marked 1/4 S. on N. side for the 1/4 sec. cor., from which
A Fir 50" dia., bears N.54°E., 31 lks. dist. mkd. 1/4 S BT.
A Fir 16" dia., bears S.16°W., 24 lks. dist. mkd. 1/4 S BT.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - May 1962 - C.S. File 51/163-1

Found - 50" Fir N.54°E., 20.5 ft., now 60" snag, bark scribed.
16" Fir S.16°W., 15.8 ft., now 38".
Set 1" x 30" Iron pipe.
Scribed- 12" D.Fir S.63 1/2°W., 28.2 ft.
19" D.Fir N.22 1/2°W., 63.0 ft.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531 - Surveyed Oct 1963/June 1964 - (DCSO records Vol. 33 Page(s) 13633-34)

The 1/4 sec. cor., recorded and remonumented in 1962 by Johnstone, with an iron pipe 1" dia., 6" above ground, firmly set, from which the original bearing trees:
A Fir 71" dia., bears N.54°E., 35 lks. dist. (31 lks. to face) mkd. 1/4 S T on a bark blaze. (Rec. dist. 31 lks.)
A Fir 48" dia., bears S.16°W., 24 lks. dist. with no marks visible.
and bearing tres mkd. by Johnstone:
A Fir 21" dia., bears N.24°W., 96 lks. dist. mkd. with a partially healed double blaze.
A Fir 12" dia., bears S.62 1/2°W., 43 lks. dist. mkd. with a partially healed double blaze.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 25" in the ground, with brass cap mkd:

T 31 S R 7 W
1/4 S 22
S 27
1964

Reset the iron pipe alongside the iron post.