

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8050)

Set a Fir post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 14, 15, 22 and 23, marked T31S R7W S14 on NE.; S23 on SE.; S22 on SW.; and S15 on NW. faces, with 2 notches on E. and 3 notches on S. edges, from which

A Fir 34" dia., bears N.5°E., 31 lks. dist. mkd. T31S R7W S14 BT.

A Fir 30" dia., bears S.36°E., 19 lks. dist. mkd. T31S R7W S23 BT.

A Fir 28" dia., bears S.77°W., 41 lks. dist. mkd. T31S R7W S22 BT.

A Chinquapin 7" dia., bears N.28°W., 34 lks. dist. mkd. T31S R7W S15 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & C. Stone, crew - Nov. 1966 - C.S. File 54/36-3

Found - 28" now 36" D.Fir, S.77°W., 27.1 ft., bark scribed.
30" now 39" D.Fir, S.36°E., 12.5 ft., bark scribed.
34" Fir, now down, N.5°E., 20.5 ft.
No trace of NW. tree.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 7 W
S 15 | S 14
S 22 | S 23
1966

New BTs- 8" D.Fir N.83°E., 17.5 ft. mkd. T31S R7W S14 CS BT.
11" Cedar N.42°W., 29.1 ft. mkd. T31S R7W S15 CS BT

Cor. Fd. and used in BLM resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #834, surveyed April/June 1974 - (DCSO records Vol. 39 Page(s) 15734)

Ron Quimby - Crew: R. Olsen & J. Leonard - 10/2017 - C.S. File 65/99-47

Found - DCSO 2½" brass cap on 1" I.Pipe. (Properly mkd)
38" burnt fir stump 6' S.36°E., 12.5 ft. good scar.
18" D.Fir N.83°E., 17.5 ft. good scar (dead)

New - 52" Fir N.7°W., 62.4 ft bark scribed T31S R7W S15 BT
Set 5/8" I.Rods with yellow plastic cap & posts:
N.66°E., 18.3 ft.
S.69°E., 23.7 ft.
S. 52°W., 15.5 ft.

Note - Compass decl. 15½°E.