

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8054)

Set a Fir post 40" long, 3" sq., 18" in the ground marked ¼ S. on W. side for the ¼ sec. cor., from which
A Cedar 16" dia., bears N.45°E., 11 lks. mkd. ¼ S BT.
A Laurel 7" dia., bears S.30°W., 10 lks. mkd. ¼ S BT.

BLM resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #834, surveyed April/June 1974 - (DCSO records Vol. 39 Page(s) 15737)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 7 W
¼
S 10 | S 11
1974

from which

A Fir 9" dia., bears N.33½°E., 37 lks. mkd. ¼ S11 BT.
A Fir 10" dia., bears N.6°W., 81 lks. mkd. ¼ S10 BT.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #834, surveyed July 1979 - (DCSO records Vol. 42 Page 16552)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

From this point, the ¼ sec. cor. of secs. 10 and 11, erroneously reestablished by Chatters in 1974, bears S.0°21'W., 0.653 chs. dist., set, marked and witnessed as described in the official record.

I remove the iron post, and destroy the marks on the bearing trees, and at the true corner point,

Reset the iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 7 W
1/4
S 10 | S 11
1979
1974

from which

A Grand Fir 8" dia., bears S.47°E., 15 lks. mkd. ¼ S11 BT.
A Cedar 12" dia., bears N.34½°W., 18½ lks. mkd. ¼ S10 BT.

(Cont. Next Page)

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ron Quimby - Crew: R. Olsen & R. Heichel - 12/2017 - C.S.
File 65/99-43

Found - BLM brass cap (properly mkd)
24" Hemlock (Orig. Grand Fir) S.47°E., 9.9 ft. good
scar.
26" burned out cedar snag N.34°W., 11.1 ft. (Rec.
18½ lks)
7" Fir N.65°W., 17.7 ft (no record)

New - 12" Fir N.8°E., 36.0 ft. scribed ¼ S11 BT
20" Fir S.32°W., 8.6 ft. scribed ¼ S10 BT

Note - Corner is approx. 80' north of small creek. Flows NE
Area badly burnt 9/2017