

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 19 Page(s) 8019)

Set post cor. to secs. 2, 3, 10 and 11, from which
 A Chinquapin 8" dia., bears N.40°E., 50 lks. dist.
 A Laurel 6" dia., bears S.40°E., 10 lks. dist.
 A Laurel 8" dia., bears S.40°W., 26 lks. dist.
 A Laurel 10" dia., bears N.50°W., 60 lks. dist.

Fd. and Used in GLO resurvey by Byars, under contract #448, dated June 13, 1882 - (DCSO records, Vol. 19 Pg. 8053)

BLM resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #834, surveyed April/June 1974 - (DCSO records Vol. 39 Page(s) 15737-38)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
 Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 7 W
<u>S 3 S 2</u>
S 10 S 11
1974

from which

- A Fir 18" dia., bears N.19°E., 18 lks. dist. mkd. T31S R7W S2 BT.
- A Fir 20" dia., bears S.54½°E., 34 lks. dist. mkd. T31S R7W S11 BT.
- A Fir 30" dia., bears S.39½°W., 83 lks. dist. mkd. T31S R7W S10 BT.
- A Fir 15" dia., bears N.53¼°W., 104 lks. dist. mkd. T31S R7W S3 BT.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #834, surveyed July 1979 - (DCSO records Vol. 42 Page(s) 16552-53)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

From this point, the cor. of secs. 2, 3, 10 and 11, erroneously reestablished by Chatters in 1974, bears S.1°21'W., 0.341 chs. dist., set, marked and witnessed as described in the official record.
 I remove the iron post, and destroy the marks on the bearing trees, and at the true corner point
 (Cont. Next Page)

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Reset the iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 7 W
S 3 S 2
S 10 S 11
1979
1974

from which

- A Cedar 17" dia., bears N.85½°E., 85 lks. dist. mkd. T31S R7W S2 BT.
- A Fir 20" dia., bears S.12¼°E., 19 lks. dist. mkd. T31S R7W S11 BT.
- A Fir 30" dia., bears S.27½°W., 109 lks. dist. mkd. T31S R7W S10 BT.
- A Fir 16" dia., bears N.73°W., 90 lks. dist. mkd. T31S R7W S3 BT.