

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8049)

Set Fir post 3 ft. long, 3" sq., 18" in the ground for ¼ sec. cor. marked ¼ S. on N. face, from which
A Fir 12" dia., bears N.10°E., 8 lks. dist. mkd. ¼ S BT.
A Fir 10" dia., bears S.65°E., 19 lks. dist. mkd. ¼ S BT.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - May 28, 1962 - C.S. File 51/163-1

Found - 12" Fir N.10°E., 5.3 ft.
Set 1¼" x 40" Iron pipe.
Scribed- 20" D.Fir S.76°W., 74.9 ft.
15" W.Fir N.76°E., 52.0 ft.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Karen Mosley, crew - Wit: Ted Davis, BLM - April 22, 1981 - C.S. File 61/19-45

Found - 1¼" x 40" I.P. firmly set 30" in the ground.
Stump hole bears N.10°E., 5.0 ft. Possibly from orig. 12" Fir.
20" now 23" Fir bears S.76°W., 74.9 ft. with well healed double blaze. This tree will be cut in future road building project.
15" now 19" Fir bears N.76°E., 52.0 ft. with well healed double blaze.
Since pipe is in good condition and firmly set, I DO NOT set a brass cap.
New BTs- 11" Fir bears N.06°E., 51.8 ft. scribed "¼ S23 CS BT" in double blaze.
10" Fir bears S.35°E., 60.4 ft. scribed "¼ S26 CS BT" in double blaze.
9" Fir bears S.87°W., 44.2 ft. scribed "¼ S26 CS BT" in double blaze.
All trees have DCSO bearing tree tags.