

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8051)

Set Laurel post 3 ft. long, 3" sq., 18" in the ground for ¼ sec. cor. marked ¼ S. on N. face, from which
A Laurel 7" dia., bears S.56°E., 26 lks. dist. mkd. ¼ S BT
A Laurel 8" dia., bears N.15°E., 23 lks. dist. mkd. ¼ S BT

Corner report by Douglas Co. Surveyors Office - John Powell and crew - (probably 1970) - C.S. File 54/36-18

Found good line, very old blazes on Fir stobs and cedars. Good call on creek, 2.80 chains from corner. A lot of very small Laurels in area, growth very slow. Some down and rotten. BTs, 7-8" Laurels, I doubt if they would be 10" now.

BLM resurvey by Owen C. Chatters II, Cadastral Surveyor, under Group #834, surveyed April/June 1974 - (DCSO records Vol. 39 Page(s) 15735)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 7 W

¼ $\frac{S \ 14}{S \ 23}$

1974

from which

A Fir 10" dia., bears N.16½°W., 13½ lks. dist. mkd. ¼ S14 BT.

A Fir 8" dia., bears S.28°E., 17 lks. dist. mkd. ¼ S23 BT.