

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8052-53)

Set a Cedar post 4 ft. long, 3" sq., 18" in the ground for ¼ sec. cor. marked ¼ S. on N. face, from which
A Fir 14" dia., bears S.21°W., 14 lks. mkd. ¼ S BT.
A Laurel 12" dia., bears N.30°E., 40 lks. mkd. ¼ S BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 680 - Surveyed April/Sept. 1969 - (DCSO records Vol. 35 Page(s) 14507-08)

The cor. of secs. 11 and 14, determined at record distance from the original bearing trees:

A root hole bears N.23°E., 40 lks., with a down Madrone 13" dia., alongside with fragmentary scribe marks visible in negative on overgrowth. (Rec. N.30°E.)

A Fir 27" dia., bears S.27°W., 14 lks., with scribe marks ¼ S BT visible on bark blaze. (Rec. S.21°W.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: ¼ $\frac{S\ 11}{S\ 14}$

T 31 S R 7 W
1969

from which new bearing trees:

A Fir 8" dia., bears N.18°E., 85 lks., mkd. ¼ S11 BT

A Fir 17" dia., bears S.59°E., 29½ lks., mkd. ¼ S14 BT.

Ron Quimby - Crew: R. Olsen & J. Leonard - 12/2017 - C.S.
File 65/99-44

Found - BLM brass cap (properly mkd)

36" Fir S.27°W., 9.2 ft. good scar

20" Fir S.59°E., 19.5 ft. good scar

12" Fir N.18°E., 56.1 ft. good scar

New - 30" Fir N.11°W., 32.4 ft. scribed ¼ S11 BT

Note - Area badly burnt 9/2017

Compass decl. 15½°E.