

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8036)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground for 1/4 sec.cor. marked 1/4 S. on W. face, from which
A Pine 15" dia., bears S.15°W., 18 lks. dist. mkd. 1/4 S BT.
A Fir 28" dia., bears S.80°E., 55 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531 - Surveyed Oct 1963/June 1964 - (DCSO records Vol. 33 Page(s) 13622)

The 1/4 sec. cor., determined at record bearing and distance from the remaining original bearing tree:

A Fir 47" dia., bears S.80°E., 55 lks. dist. mkd. 1/4 S BT on a bark blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 31 S R 7 W

1/4

S 35 S 36

1964

from which new bearing trees

A Fir 9" dia., bears N.68 3/4°E., 64 1/2 lks. dist. mkd. 1/4 S36 BT.

A Fir 14" dia., bears S.54 3/4°W., 29 lks. dist. mkd. 1/4 S35 BT.

Survey by Mark Smalley, L.S. #2354 - For: Kenneth Ford - July 1994 - M 120-43

Found - 1964 Cad. BCIP

48" Fir, S.80°E., 36.3', bark scribe.

18" Fir, S.55°W., 19.1', healed

New BTs -17" Fir, N.29°W., 30.2' "1/4 S BT"

9" Fir, S.86°W., 15.3', "1/4 S BT"