

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8042)

Set a Laurel post, 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor. marked 1/4 S. on W. face, from which
A Fir 42" dia., bears N.50°E., 16 lks. dist. mkd. 1/4 S BT
A Fir 36" dia., bears S.45°W., 50 lks. dist. mkd. 1/4 S BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Cliff Stone, crew - Dec/ 1966 - C.S. File 54/36-8

Found - 42" D.Fir, now snag, N.50°E., 10.6 ft., bark scribed.
36" D.Fir, now snag, S.45°W., 33.0 ft., old axe work, but no scribing.

Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 7 W
1/4 S14|S13
1966

New BTs -8" Cedar S.52 1/2°E., 11.2 ft. mkd. 1/4 S13 CS BT.
9" D.Fir N.61 1/2°W., 34.7 ft. mkd. 1/4 S14 CS BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 680 - Surveyed April/Sept. 1969 - (DCSO records Vol. 35 Page(s) 14501-02)

The 1/4 sec. cor., perpetuated and recorded by the County in 1966, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground with 1966 brass cap from which the original bearing trees:

A Fir snag 50" dia., bears N.50°E., 19 lks., with scribe marks 1/4 S BT visible on bark blaze. (Rec, 16lks.)

A Fir snag 45" dia., bears S.45°W., 52 lks. dist., with no marks remaining on burned bark blaze. (Rec. 50 lks.)

and bearing trees mkd. by the County:

A Cedar 10" dia., bears S.52 1/2°E., 18 lks. dist. with scribe marks 1/4 S13 CS BT visible on open blaze.

A root hole bears N.61 1/2°W., 52 lks. dist., with a down Fir 8" dia., alongside, with scribe marks 1/4 S14 CS BT visible on open blaze.

and new bearing trees:

A Fir 9" dia., bears S.15 1/2°E., 33 1/2 lks. dist., mkd. 1/4 S13 BT.

A Fir 25" dia., bears N.8 1/4°W., 53 lks. dist., mkd. 1/4 S14 BT.

continued next page

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ron Quimby - Crew: R. Olsen & J. Leonard - 12/2017 - C.S.
File 65/99-45

Found - DCSO 2½" brass cap (properly mkd)
50" burnt fir stump N.50°E., 12.5 ft. (no marks)
45" burnt fir stump S.45°W., 34.3 ft. (no marks)
14" burnt fir stump S.15½°E., 22.1 scar
29" burnt fir stump N.8¼°W., 35.0 scar
New - 8" Fir N.30°W., 8.8 ft. scribed ¼ S14 BT
6" Fir N.36°E., 9.0 ft. scribed ¼ S13 BT
6" Fir S.17°W., 18.9 ft. scribed ¼ S14 BT
5" Fir S.22°E., 16.1 ft. scribed ¼ S13 BT
Note - Corner is approx 300' east of small creek that flows
north.
Area badly burnt 9/2017
Compass decl. 15½°E.