

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 19 Page(s) 8019)

-----  
Set ¼ sec. post, from which  
A Laurel 24" dia., bears S.85°E., 85 lks.  
A Cedar 24" dia., bears N.42°W., 58 lks.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 680 - Surveyed April/Sept. 1969 - (DCSO records Vol. 35 Page(s) 14506-07)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: ¼  
S 2 S 1  
T 31 S R 7 W  
1969

from which  
A Fir 20" dia., bears N.42°E., 15 lks. dist. mkd. ¼ S1 BT.  
A Fir 7" dia., bears N.37°W., 34 lks. dist. mkd. ¼ S2 BT.

BLM corrective dependent resurvey by James E. Jelley, Cadastral Surveyor, under Group #680, surveyed June 1977 - (DCSO records Vol. 41 Page(s) 16262-63)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
From this point, the ¼ sec. cor. of secs. 1 and 2, erroneously reestablished by Jelley, in 1969, bears S.5°24'W., 0.075 chs. dist., set, mkd. and witnessed as described in the official record.  
I remove the iron post, destroy the marks on the bearing trees, and at the proportionate corner point, Reset the iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: ¼  
S 2 S 1  
T 31 S R 7 W  
1977  
1969

from which  
A Fir 18" dia., bears S.45 3/4°E., 79½ lks. dist. mkd. ¼ S1 BT.  
A Fir 9" dia., bears N.55°W., 39 lks. dist. mkd. ¼ S2 BT.

Fd. OK, June 1988 by H. Johnstone - M 106-52