

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8043)

Set Fir post 3 ft. long, 3" sq., 18" in the ground for 1/4 sec. cor. marked 1/4 S. on N. face, from which

A Fir 16" dia., bears N.26°E., 23 lks. dist. mkd. 1/4 S BT.

A Fir 12" dia., bears S.12°W., 39 lks. dist. mkd. 1/4 S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Dec. 1962 - C.S. File 49/109-12

Found - Both orig. BTs. Orig. SW. BT, previously opened, shows good scribing.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 7 W

1/4 S 12

S 13

1962

New BTs - 23" Cedar bears S.59°E., 40.6 ft. scribed 1/4 S13 CS BT.

Rescribe orig. NW. 36" R.Fir, N.26°E., 17.2 ft. "1/4 S12 CS BT"

Cor. Fd. and used in BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 680 - Surveyed April/Sept. 1969 - (DCSO records Vol. 35 Page(s) 14503)

Ron Quimby - Crew: R. Olsen & J. Leonard - 9/2017 - C.S. File 65/99-9

Found - DCSO brass cap (properly mkd)

36" Cedar S.59°E., 40.6 ft., healed face.

New - 22" D.Fir S.19°W., 13.0 ft., scribed 1/4 S13 BT

18" D.Fir N.29°W., 7.3 ft., scribed 1/4 S12 BT

12" D.Fir N.44°E., 15.6 ft., scribed 1/4 S12 BT

Note - Corner is approx. 100' E of road.

Area badly burnt 9/2017

Compass decl. 15 1/2°E.