

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; and 12, T31-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8107)

Set a Cedar post 3 ft. long, 3" sq., 20" in the ground, mkd. 1/4 S for the 1/4 sec. cor., and from which
A Fir 48" dia., bears S.44°E., 26 lks. dist. mkd. 1/4 S BT
A Fir 42" dia., bears West, 20 lks. dist. mkd. 1/4 S BT.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8242)

Post gone. Witness trees standing and agree with notes furnished by the Surveyor General. Set a Fir post 4 ft. long, 4" sq., 24" in the ground mkd. S7 on E. and S12 1/4 S on W. faces, for the 1/4 sec. corner. Point established from the witness trees.

BLM Resurvey by C. Albert White, Harold D. Corbin, Cadastral Surveyors and Donald R. Beck, Surveying Technician, Under Group #446, Surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 31 Page(s) 13187)

The 1/4 sec. cor., determined at record brg. and dist. from the original bearing trees:

A Fir 56" dia., bears S.44°E., 26 lks. dist., mkd. with visible bark scribing 1/4 and cruiser marks.
A Fir 47" dia., bears West, 20 lks. dist. mkd. with a healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

1/4
S 12 | S 7
R 9 W | R 8 W
T 31 S
1962

from which new bearing trees:

A Fir 12" dia., bears N.63 1/2°E., 54 lks. dist., mkd. 1/4 S7 BT.
A Fir 55" dia., bears N.80°W., 50 lks. dist., mkd. 1/4 S12 BT on bark blaze.

Douglas Co. Surveyors Office - Greg Quibell, Deputy - Debbie Stewart, crew - Feb. 19, 1981 - C.S. File 61/19-7

Found - 1962 BLM brass cap in good condition, buried in the ground approx. 8", properly stamped.
(Cont. Next Page)

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 cor. for sec. 7; and 12, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Stump of orig. 42" now 47" Fir with BLM BT tag, bears West, 13.2 ft. to the face.
Stump of orig. 48" Fir (sec. 7) which has rolled over and slid down hill almost on top of the cap.
New Accessories:
Set boat spike in top of orig. sec. 12 BT stump which is now 47". Spike bears West, 14.5 ft.
Set boat spike in top of 48" Fir stump which bears N.38°E., 66.9 ft.
Both stumps have new BT tags. No trees suitable for scribing are in the vicinity.

Kris DeGroot - For: Roseburg Resources - 6/2001 - M 137-13

Found - 2½" iron post, USBLM in 1962, firmly set flush w/ground w/3¼" USBLM brass cap properly mkd. From which OBTs by Byars in 1882:
A root hole bears S.44°E., 17.2 ft. w/uprooted 56" D.Fir stump lying on the North edge of the BCIP.
47" Fir stump bears West 13.2 ft to face, 14.2 ft to bridge spike (1981 rec 14.5 ft to bridge spike)
BT by White & Corbin in 1962
56" Fir stump bears N.80°W., 32.5 ft. no scribing visible (Rec. 50 lks.)
BT by Quibell, DCSO in 1981
48" Fir stump which bears N.38°E., 66.9 ft. to a boat spike.
New BTs- 6" D.Fir bears S.31°E., 16.5 ft. scribed "¼ S7 BT"
9" W.Fir bears S.76°W., 22.0 ft. scribed "¼ S12 BT"
Note- All new BTs have double blazed faces w/brass washer stamped "PLS 1941" nail into the lower blaze. Bearings are taken to the center of the tree at the root crown & distances are measured to a nail in the root crown at the center of the tree all BTs have a 6" red band painted around the tree & the blazed face painted red & BT signs nailed to the tree.

Ron Quimby - 12/2/2016 - C.S. File 65/93-61

Found - BLM brass cap
BTs per M137-13
New - A 6" D.Fir N.72°W., 8.4 ft. scribed ¼ S12 BT.
A 8" D.Fir N.64°E., 19.8 ft. scribed ¼ S7 BT.

continued next page

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; and 12, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 2-11-25 - C.S. File 67/60-5 -

Found - BLM 1962 - Brass Cap
47"x2ft Fir stump W. 14.2ft to bridge spike in top.
56"x2½ft Fir stump N.80°W. 32.5ft prev. opened blaze
8" D.Fir S.31°E. 16.5ft fully healed double blaze.
Add 3½" mag nail right side center.
13"x7ft sawn W.Fir stump S.76°W. 22.0ft. Fully
healed double blaze. Add 3½" mag nail right side
center.
6"W.Fir N.72°W. 8.4ft. Partly healed single blaze.
All scribes visible. Add 3½" mag nail right side
center.
9"D.Fir N.64°E. 20.2ft (Rec 19.8ft) partly healed
single blaze illegible scribes visible. Add 3½"
mag nail right side center.

Notes - Mon on moderate N.N.W. slope just North of large
bench SW quadrant clearcut, rest old growth.

Compass decl. 14½°E.
OGRS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N 42° 53'00.591 W 123° 42'07.021