

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8154)

Set a fir post 3 ft. long, 3" sq., 18" in the ground, marked 1/4 S on N side for the 1/4 sec. cor., from which
A live Oak, 8" dia., bears N.53°E., 18 lks., mkd: 1/4 S BT.
A fir, 12" dia., bears S.12°E., 22 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - M. Godfrey - S.A. Bilow - Aug. 1958 - C.S. File 49/109-4

Found - Orig. 12" now 24" Fir S.12°E., 14.5 ft., previously opened, shows good scribing "1/4 S"
No trace of orig. NE BT.
Set brass cap at corner mkd: 1/4 S20 T31S R8W County Surveyors Office 1958
New BTs- 12" Cedar bears N.46°E., 45.0 ft scribed 1/4 S20 CS BT
I rescribe orig. SE BT 1/4 S29 CS BT.

Fd. Ok by S.P. Ness, Dec. 1981, M89-65

Ray Wytcherley - For: Swanson Group, Inc. - Jan. 2006 - M149-44

Found - 1958 DC BC, from which
Remaining orig. BT: 38" dia., D.Fir bears S.12°E.
14.5 BT per C.S. 49/109
13" dia., cedar bears N.46°E., 45.0 ft.
New - 8" dia., D.Fir bears N.10°W., 29.81 ft. scribed "S20 1/4 BT"
6" dia., D.Fir bears S.81°W., 24.84 ft. scribed "S29 1/4 BT"