

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8162)

Marked a hemlock post 3 ft. long, 3" sq., 18" in the ground 1/4 S for the 1/4 sec. cor., from which
 A hemlock, 14" dia., bears East, 20 lks., mkd: 1/4 S BT
 A hemlock, 12" dia., bears S.85°W., 33 lks., mkd: 1/4 S BT.

BLM dependent resurvey by C. Albert White, Harold D. Corbin, Cadastral Surveyors and Donald R. Beck, Survey Technician, under Group #350, surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 32 Page(s) 13209-10)

The 1/4 sec. cor. of secs. 5 & 8, determined at record bearing and distance from the remains of the original bearing trees;
 A stump hole, with roots of a hemlock remaining, bears East, 20 lks.
 A hemlock, 16" dia., bears S.85°W., 33 lks., with old axe marks visible on opened blaze
At the corner point
Set an iron post, 28" long, 4" dia., 25" in the ground, with brass cap mkd:
 1/4 $\frac{S}{S} \frac{5}{8}$
 T31S R8W
 1961
from which new BTs
 A hemlock, 8" dia., bears N.3 1/2°W., 48 lks., mkd: 1/4 S5 BT.
 A hemlock, 10" dia., bears S.18°W., 17 lks., mkd: 1/4 S8 BT.

BLM dependent resurvey by Charles E. Akin, Jr., Cadastral Surveyor, under Group No. 819, surveyed Aug./Oct. 1972 - (DCSO Records Vol. 36 Page(s) 14935-6)

The 1/4 sec. cor., of secs. 5 & 8, monumented with an iron post, 2 1/2" dia., firmly set, protruding 6" above ground, with brass cap (properly) mkd.
from which the remains of the original bearing trees
 A stump hole, with roots of a hemlock remaining, bears East, 20 lks.
 A hemlock, 17" dia., bears S.85°W., 33 lks., with old axe marks visible on opened blaze.
and bearing trees marked by White, Corbin, and Beck.
 A hemlock, 10" dia. bears N.3 1/2°W. 48 lks. with fragmentary scribe marks visible on partially healed blaze.
 A hemlock, 12" dia. bears S.18°W. 17 lks. with fragmentary scribe marks visible on partially healed blaze.

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Daniel A Renton, Minister-Glaeser Surveying - Garrett Finch & Crew - For: US Department of Interior, BLM - Snake Eyes - Task H - June 2023 - M178-75 A-E

Found - A 3¼" BLM brass cap (properly mkd) 0.6 ft above ground from which:
A 14" snag (60 ft high) bears S.18°W., 10.5 ft with healed double blaze and BT sign (1960)
A rotted stump (30" high) bears S.82°W., 22.8 ft. (1973)

New - A 15" hemlock bears S.46°W., 9.9 ft mkd: ¼ S8 BT.
A 15" Fir bears N.57°E., 8.7 ft mkd: ¼ S5 BT.

Set chaining nail at side center, BT signs on front and rear, and painted red band for existing BTs

Set chaining nail at side center, nail and washer stamped "PLS 2830" at base of blaze, BT signs on front and back and painted red band for new BT.