

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8145)

Set a Fir post 3 ft. long, 3" sq., 18" in the ground, marked 1/4 S on the N side, for the 1/4 sec. cor., from which
A fir, 36" dia., bears East, 62 lks., mkd: 1/4 S BT
A fir, 30" dia., bears West, 51 lks., mkd: 1/4 S BT

BLM dependent resurvey by C. Albert White, Harold D. Corbin, Cadastral Surveyors and Donald R. Beck, Survey Technician, under Group #350, surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 32 Page(s) 13211)

The 1/4 sec. cor. of secs. 16 & 17, determined at record bearing and distance from the original bearing trees:
A fir snag, 40" dia., bears East, 62 lks., to face, with no marks visible.
A fir, 45" dia., bears West, 51 lks., to face, with visible scribe marks on double bark blaze. Remarkd 1/4 S17 BT.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground with brass cap mkd.

1/4
S 17 | S 16
T31S | R8W
1962

from which a new bearing tree
A fir, 10" dia., bears S.37 1/2°E., 46 lks., mkd. 1/4 S16 BT.

Mark Smalley - For: Roseburg Forest Products - 10/14/2003 - C.S. File 65/48-44

Found - 1962 BLM IPBC
23" Fir S.37 1/2°E., 29.5' to nail (rec. 30.4') good - healed.
Orig. Fir East 40.9' stump
Orig. 47" Fir West 34.7' to nail (rec 33.7') partial scribe.

New - 16" Fir S.57°W., 23.5' scribed "1/4 S BT"
15" Fir N.80°W., 20.6' scribed "1/4 S BT"